

Figure - Bug #116570

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT2】【控制中心】未去掉闹钟的控件

2023-02-27 15:56 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-02-27
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230228
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-28
Reproducibility:	Every time	Root cause:	删除控制中心闹钟组件
Test Type:	ST		

Description
【前提条件】
1、设备已开机
【测试步骤】
1、打开控制中心
2、点击编辑图标
3、查看已有的控件
【预期结果】
3、闹钟的控件已经去掉
【实际结果】
3、仍有闹钟的控件

History

#1 - 2023-02-27 20:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184614	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Delete alarm tileTC-RID: 1201-0201903IssueID: TS-R-BUG-116570Change-Id: Ie9d70034b9069a7273328e0597915b1a8e955261			

#2 - 2023-02-27 20:34 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CDTs_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-28
- Root cause set to 删除控制中心闹钟组件

#3 - 2023-02-28 14:47 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

【验证版本】
FlatBuild_HH_MCE_FSE.M.R.user.01.00.0078.C101

【验证情况】
闹钟控件已经去掉

【验证结果】
pass

#4 - 2023-02-28 14:47 - CDTS_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

Files			
20230227-151537.jpg	200 KB	2023-02-27	CDTS_Test 吴诗雨