

Figure - Bug #116572

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting
【AF】【EVT2】【设置】设置中滚动条与ui图不符
2023-02-27 16:30 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-02-27
Priority:	Normal	Due date:	2023-03-01
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230227
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-02-28
Test Type:	ST	Root cause:	UI 适配问题。

Description	
【前提条件】 1、设备正常启动	
【测试步骤】 1、进入设置 2、查看滚动条	
【预期结果】 2、与ui图设计一致，滚动条不会遮盖列表	
【实际结果】 2、滚动条遮盖了列表右侧	
【复现率】 3/3	

History

#1 - 2023-02-28 10:44 - CD FW-廖涛
- Due date set to 2023-03-01

#2 - 2023-02-28 18:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184848	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix scollbar style problem.TC-RID: 1201-0201813IssueID: TS-R-BUG-116572Change-Id: I10e0c8f0dbf5bf8f3d8732f19c68e3204f176b2f			

#3 - 2023-02-28 18:59 - CD FW-廖涛
- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨
- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-28
- Root cause set to UI 适配问题。

■ Current conclusion

已处理，代码已入库。

■ My analysis

UI 适配问题。

■ Next action

测试验证。

#4 - 2023-03-02 10:27 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

【验证版本】

FlatBuild_HH_MCE_FSE.M.R.user.01.00.0079.C101

【验证情况】

滚动条与ui相符

【验证结果】

pass

#5 - 2023-03-02 10:27 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
screenshot-20230227-150624.png	191 KB	2023-02-27	CDTS_Test 吴诗雨
ui图.jpg	356 KB	2023-02-27	CDTS_Test 吴诗雨