

Figure - Bug #116752

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111051 (New): AF-V2.0-Launcher/SystemUI-通知中心

【AF】【EVT】【通知中心】点击一个应用的隐藏通知，页面跳转时，右上角状态栏短暂闪过所有有隐藏通知的应用图标

2023-03-06 17:09 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-06
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230306
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230306
Severity:	Normal	Fixed Version:	2023-03-13
Reproducibility:	Every time	Root cause:	删除了隐藏通知的状态栏图标
Test Type:	ST		
Description			
【前提条件】			
1、设备正常启动			
【测试步骤】)			
1、使用测试软件发送几条通知			
2、点击隐藏通知内容部分			
【预期结果】			
2、正常跳转到应用页面			
【实际结果】			
2、页面跳转时，右上角状态栏短暂闪过所有有隐藏通知的应用图标			
【复现率】			
3/3			

History

#1 - 2023-03-10 16:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186728	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Icons for hidden notifications should not be added to the status barTC-RID: 1201-0201902IssueID: TS-R-BUG-116752Change-Id: Icd336a397d7ce9ba10aa4eb208c3829412ceb895			

#2 - 2023-03-10 16:46 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-13
- Root cause set to 删除了隐藏通知的状态栏图标

#3 - 2023-03-11 13:03 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303110019

3.11
验证通过

#4 - 2023-03-11 13:03 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190078 2023-03-06 17-07-57.mp4	8.74 MB	2023-03-06	CD TEST-方永红