

Figure - Bug #116761

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI---Setting

【AF】 【EVT】 【设置】修改启用时机后返回上一页显示启用时机是修改前的值，退出屏保页再次进入显示正确

2023-03-06 19:48 - CD TEST-方永红

|                                                     |             |                   |                                                   |
|-----------------------------------------------------|-------------|-------------------|---------------------------------------------------|
| Status:                                             | CLOSED      | Start date:       | 2023-03-06                                        |
| Priority:                                           | Normal      | Due date:         |                                                   |
| Assignee:                                           | CD TEST-方永红 | % Done:           | 100%                                              |
| Category:                                           | CD-FW       | Estimated time:   | 0.00 hour                                         |
| Target version:                                     |             | Found Version:    | FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230309 |
| Need_Info:                                          | --          | Degrated:         | No                                                |
| Resolution:                                         | FIXED       | Verified Version: | FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230309 |
| Severity:                                           | Normal      | Fixed Version:    | 2023-03-09                                        |
| Reproducibility:                                    | Every time  | Root cause:       | Settings 两栏适配遗漏。                                  |
| Test Type:                                          | ST          |                   |                                                   |
| Description                                         |             |                   |                                                   |
| 【前提条件】<br>设备开机                                      |             |                   |                                                   |
| 【测试步骤】<br>1.进入设置-屏保-启用时机页面<br>2、切换启用时机<br>3、返回上一级页面 |             |                   |                                                   |
| 【预期结果】<br>3.启用时机显示步骤二中设置的值                          |             |                   |                                                   |
| 【实际结果】<br>3.修改启用时机后返回上一页显示启用时机是修改前的值，退出屏保页再次进入显示正确  |             |                   |                                                   |

History

#1 - 2023-03-08 14:51 - CD FW-廖涛

- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#2 - 2023-03-09 09:39 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                               | Project                                     | Branch                                        | Uploader                 |
|--------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------|--------------------------|
| 186424                                                                                                                                           | general/platform/packages/apps/Settin<br>gs | Pre_figure_turbox-c2130c-la1.1-qssi12<br>-dev | tao.liao@thundersoft.com |
| AF:Settings: Fix preference status sync problem.TC-RID: 1201-0201806IssueID: TS-R-BUG-116761Change-Id: If73267c66b043ed6ab3adb491f4e2377f3e59f45 |                                             |                                               |                          |

#3 - 2023-03-09 09:40 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-09
- Root cause set to Settings 两栏适配遗漏。

■ Current conclusion

已处理，代码已入库。

■ My analysis

Settings 两栏适配遗漏。

■ Next action

测试验证。

#4 - 2023-03-11 13:05 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild\_HH\_MCE\_FSE.M.D.user.01.00.C101.202303110019

3.11

验证通过

#5 - 2023-03-11 13:05 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

|                                            |         |            |             |
|--------------------------------------------|---------|------------|-------------|
| Phone-STS40X190078 2023-03-06 19-47-26.mp4 | 9.23 MB | 2023-03-06 | CD TEST-方永红 |
|--------------------------------------------|---------|------------|-------------|