

Figure - Bug #116762

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI---Setting

【AF】 【EVT】 【设置】 设置-关于本机-修改设备名称后详情页和设置列表中关于本机名称显示不一致

2023-03-06 19:52 - CD TEST-方永红

|                                                        |             |                   |                                                   |
|--------------------------------------------------------|-------------|-------------------|---------------------------------------------------|
| Status:                                                | CLOSED      | Start date:       | 2023-03-06                                        |
| Priority:                                              | Normal      | Due date:         |                                                   |
| Assignee:                                              | CD TEST-方永红 | % Done:           | 100%                                              |
| Category:                                              | CD-FW       | Estimated time:   | 0.00 hour                                         |
| Target version:                                        |             | Found Version:    | FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230308 |
| Need_Info:                                             | --          | Degrated:         | No                                                |
| Resolution:                                            | FIXED       | Verified Version: | FlatBuild_HH_MCE_FSE.M.R.user.01.00.0081.C101     |
| Severity:                                              | Normal      | Fixed Version:    | 2023-03-08                                        |
| Reproducibility:                                       | Every time  | Root cause:       | 二级页面名称修改后未同步到一级页面的描述导致                            |
| Test Type:                                             | ST          |                   |                                                   |
| Description                                            |             |                   |                                                   |
| 【前提条件】<br>设备开机                                         |             |                   |                                                   |
| 【测试步骤】<br>1.进入设置-关于本机页面<br>2、修改设备名称<br>3、观察关于本机下方的设备名称 |             |                   |                                                   |
| 【预期结果】<br>3.关于本机下方的设备名称同步骤二中修改的值一致                     |             |                   |                                                   |
| 【实际结果】<br>3.修改设备名称后详情页和设置列表中关于本机名称显示不一致                |             |                   |                                                   |

History

#1 - 2023-03-07 09:48 - CD FW-廖涛

- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#2 - 2023-03-08 14:28 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                                                                                                        | Project                                     | Branch                                        | Uploader                 |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------|--------------------------|
| 186058                                                                                                                                                                                                                                    | general/platform/packages/apps/Settin<br>gs | Pre_figure_turbox-c2130c-la1.1-qssi12<br>-dev | tao.liao@thundersoft.com |
| AF:Settings: Fix device name is not sync after changed.1. Fix device name is not sync after changed;2. Fix Edittext background .9.png;TC-RID:<br>1201-0201810IssueID: TS-R-BUG-116762Change-Id: I1436ae9cd1c98b83e2373075b3b4c51aba4d9ae0 |                                             |                                               |                          |

#3 - 2023-03-08 14:30 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-08
- Root cause set to 二级页面名称修改后未同步到一级页面的描述导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

二级页面名称修改后未同步到一级页面的描述导致。已处理。

■ Next action

测试验证。

#4 - 2023-03-10 11:22 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild\_HH\_MCE\_FSE.M.R.user.01.00.0081.C101

3.10  
验证通过

#5 - 2023-03-10 11:23 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

|          |        |            |             |
|----------|--------|------------|-------------|
| 1949.png | 156 KB | 2023-03-06 | CD TEST-方永红 |
|----------|--------|------------|-------------|