

Figure - Bug #116825

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111053 (New): AF-V2.0-Launcher/SystemUI-控制中心-2音量调节

【AF】【EVT】【音量调节】使用遥控器调节音量时，唤出副屏边缘的音量调节条，点击调节条上方的铃图标,会弹出震动和来电静音的选项

2023-03-09 11:00 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-09
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0081.C101
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230309
Severity:	Normal	Fixed Version:	2023-03-13
Reproducibility:	Every time	Root cause:	删除了ringer按钮，并优化了VolumeDialog的UI显示
Test Type:	ST		
Description			
【前提条件】			
1、设备正常启动			
【测试步骤】			
1、设备连接遥控器			
2、使用遥控器调节音量			
3、点击副屏边缘的音量调节条上方的铃图标			
【预期结果】			
3、会弹出震动和来电静音的选项，副屏不支持这两项功能，建议删除相关选项和提示			
【实际结果】			
3、会弹出震动和来电静音的选项			
【复现率】			
3/3			

History

#1 - 2023-03-10 16:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186714	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: remove the ringer button and adjust the UI displayTC-RID: 1201-0201903IssueID: TS-R-BUG-116825Change-Id: I6e94f941efb7be6223fb8f7a2bfa737b12407505			

#2 - 2023-03-10 16:52 - CD FW 曹覃刚

- Status changed from New to RESOLVED

- Assignee changed from CD FW 曹覃刚to CD TEST-方永红

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-13
- Root cause set to 删除了ringer按钮，并优化了VolumeDialog的UI显示

#3 - 2023-03-11 13:06 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303110019

3.11

验证通过

#4 - 2023-03-11 13:06 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
20230309-105927.mp4	2.1 MB	2023-03-09	CD TEST-方永红