

Figure - Bug #116923

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】 【EVT】 【设置】 进入设置-系统-手势-手势导航-设置-调节灵敏度页面，灵敏度文字显示不清楚

2023-03-13 15:26 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-13
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.20230315
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Severity:	Normal	Fixed Version:	2023-03-15
Reproducibility:	Every time	Root cause:	对话框样式问题。
Test Type:	ST		

Description	
【前提条件】 1、设备正常启动	
【测试步骤】 1、进入设置-系统-手势-手势导航-设置-调节灵敏度页面	
【预期结果】 1、页面内容显示完整清晰	
【实际结果】 1、灵敏度文字显示不清楚	

History

#1 - 2023-03-14 19:13 - CD FW-廖涛

- Status changed from New to ASSIGNED

- % Done changed from 0 to 80

- Root cause set to 对话框样式问题。

■ Current conclusion

已处理，代码已提交，等待 Review。

■ My analysis

对话框样式问题。

■ Next action

代码 Review 入库。

#2 - 2023-03-14 19:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187516	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:Settings: Fix gesture edge select dialog style problem.TC-RID: 1201-0201813IssueID: TS-R-DF-116923Change-Id: I30cd1a0ca7547326bce49c2418664b29355dd4a5

#3 - 2023-03-14 19:49 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 80 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-14

■ Current conclusion
已处理，代码已入库。

■ My analysis
--

■ Next action
测试验证。

#4 - 2023-03-15 11:32 - CD FW-廖涛

- Status changed from RESOLVED to VERIFIED
- Assignee changed from CD TEST-方永红 to CD FW-廖涛

#5 - 2023-03-15 11:33 - CD FW-廖涛

- Resolution changed from FIXED to --

#6 - 2023-03-15 11:33 - CD FW-廖涛

- Status changed from VERIFIED to VERIFY_FAILED

#7 - 2023-03-15 11:34 - CD FW-廖涛

- Status changed from VERIFY_FAILED to ASSIGNED

#8 - 2023-03-15 16:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187658	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix single select dialog item textcolor problem.TC-RID: 1201-0201813IssueID: TS-R-BUG-116923Change-Id: I1a8a1a26275acb4fb482f3e9318da9c12bd2a368			

#9 - 2023-03-15 16:15 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红

- Resolution changed from -- to FIXED
- Fixed Version changed from 2023-03-14 to 2023-03-15

■ Current conclusion
已处理，代码已入库。

■ My analysis
--

■ Next action
测试验证。

#10 - 2023-03-16 10:00 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101).202303150042

3.16
验证通过

#11 - 2023-03-16 10:00 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
1524.png	167 KB	2023-03-13	CD TEST-方永红