

Figure - Bug #116947

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111055 (New): AF-V2.0-Launcher/SystemUI-控制中心-4播放器

【AF】【EVT】【音乐播放器】打开荔枝app，播放广播，音乐播放器显示异常

2023-03-14 19:28 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-14
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0082.C101(X101)
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Reproducibility:	Every time	Fixed Version:	2023-03-16
Test Type:	ST	Root cause:	第三方音乐应用发送的控制顺序和我们的设计不兼容
Description			
【前提条件】			
1、设备正常启动			
【测试步骤】			
1、使用荔枝播放广播			
2、打开控制中心			
【预期结果】			
2、控制中心音乐播放器显示正常			
【实际结果】			
2、音乐播放器的部分按钮显示异常			
【复现率】			
3/3			

History

- #1 - 2023-03-15 17:07 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
 - Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#2 - 2023-03-16 19:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187971	general/platform/packages/apps/SnapdragonMusic	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:SnapdragonMusic:Opt send notification action button.TC-RID: 1201-0301201IssueID: TS-R-BUG-116947Change-Id: Iedbaed2d59f16ab81b2db7c61150fc579df46773			

#3 - 2023-03-16 19:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187972	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:SystemUI: Fix music controller action button problem.TC-RID: 1201-0201903IssueID: TS-R-BUG-116947Change-Id: I323c1d955c7fcd9ceae220a7c25056fb8d4751d7			

#4 - 2023-03-16 19:39 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-16
- Root cause set to 第三方音乐应用发送的控制顺序和我们的设计不兼容导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

第三方音乐应用发送的控制顺序和我们的设计不兼容导致。已针对第三方音乐应用进行适配，若后续再有第三方音乐应用音乐控制有问题，可能需要单独适配。

音乐控制按钮的样式（包含颜色大小）由第三方音乐应用提供，系统无法修改，所以不做适配处理。

■ Next action

测试验证。

#5 - 2023-03-20 16:57 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101).202303191230

3.20

验证通过

#6 - 2023-03-20 16:57 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
20230314-192019.jpg	195 KB	2023-03-14	CD TEST-方永红