

Figure - Bug #117015

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【控制中心】进入控制中心编辑模式，轻微向上滑动，完成按钮下方会出现一条多余的线

2023-03-18 14:11 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-18
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0085.C101(X101)
Severity:	Normal	Fixed Version:	2023-03-23
Reproducibility:	Every time	Root cause:	由于可滚动造成了该现象，已禁止滚动
Test Type:	ST		
Description			
【前提条件】 设备已开机			
【测试步骤】 1、打开控制中心 2、进入编辑模式 3、轻微向上滑动			
【预期结果】 3、页面显示正常			
【实际结果】 3、完成按钮下方会出现一条多余的线			

History

#1 - 2023-03-21 19:41 - CD FW 曹覃刚
- Status changed from New to ASSIGNED

■ 我的分析

已确认能够在VX1上复现该问题
在VX1上，编辑模式可以滑动，导致显示异常，实际应该不能够滑动

■ 下一步解析计划

检查该部分的滑动控制

#2 - 2023-03-22 09:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188929	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com

- #3 - 2023-03-22 09:38 - CD FW 曹覃刚
- Status changed from ASSIGNED to RESOLVED
 - Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Fixed Version set to 2023-03-23
 - Root cause set to 由于可滚动造成了该现象，已禁止滚动

- #4 - 2023-03-23 11:09 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
 - Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0085.C101(X101)

3.23
验证通过

- #5 - 2023-03-23 11:09 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
1406.png	187 KB	2023-03-18	CD TEST-方永红