

Figure - Bug #117024

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT3】【设置】通知-应用设置-音乐的所有通知页面，应用名称显示有问题，逐级返回后再次应用通知时，会出现设置闪退的现象

2023-03-18 15:54 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-18
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Severity:	Major	Fixed Version:	2023-03-21
Reproducibility:	Every time	Root cause:	带 Channel 信息的通知详情对 Channel Id 传递的处
Test Type:	ST		
Description			
【前提条件】 设备已开机			
【测试步骤】 1、打开设置-通知-应用通知 2、选择音乐 3、点击com.android.music这条通知 4、点击页面中的音乐图标 5、点击返回按钮至应用通知页面 6、再次点击应用通知			
【预期结果】 3、通知名称为“ 音乐 ” 4、点击音乐图标后页面无变化 6、正常进入下一级页面			
【实际结果】 3、通知名称为“ com.android.music ” 4、点击音乐图标后页面变化 6、设置闪退			

History

#1 - 2023-03-20 14:55 - CD FW-廖涛
- Priority changed from High to Normal

■ My analysis

经过分析，音乐通知通知展示包名，为 AOSP 原生逻辑，跳转后标题变化和之前处理音乐、视频区分逻辑有关系，需要重新梳理下看怎么处理。

关于崩溃问题，已经在处理 <https://share.thundersoft.com/redmine/issues/117016> 的时候一并处理了，所以先将该 BUG 的优先级降为 Normal。

■ Next action

进一步分析音乐的通知逻辑及展示情况。

#2 - 2023-03-21 19:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188816	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix notification title and page header problem.TC-RID: 1201-0201803IssueID: TS-R-BUG-117024Change-Id: I4941ebd6adeabcdnf8ab62a7358cd07c40fec94fb			

#3 - 2023-03-21 19:27 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-21
- Root cause set to 带 Channel 信息的通知详情对 Channel Id 传递的处理逻辑有问题导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

带 Channel 信息的通知详情对 Channel Id 传递的处理逻辑有问题导致。

通过调整 Channel 通知页面跳转方式，处理页面参数传递问题。

■ Next action

测试验证。

#4 - 2023-03-24 13:56 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102).202303240240

3.24

验证通过

#5 - 2023-03-24 13:56 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Phone-STs40X190078 2023-03-18 15-09-22.mp4	29.5 MB	2023-03-18	CD TEST-方永红
settings.txt	6.68 MB	2023-03-18	CD TEST-方永红