

Figure - Bug #117050

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT3】【设置】设置中的静音图标在设备重启后变为非静音图标

2023-03-21 10:15 - CD Test赵飞

Status:	CLOSED	Start date:	2023-03-21
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101(X101)
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-03-22
Test Type:	ST	Root cause:	AOSP 原生问题。AudioService 初始 mute 状态数据

Description	
【前提条件】	
1、设备正常启动	
2、已正常连接中控	
【测试步骤】)	
1、打开设置 - 声音	
2、滑动音量调节条至最左侧（静音）	
3、重启设备	
4、再次进入设置 - 声音中查看	
【预期结果】	
4、页面中音量调节条左侧的图标仍然显示为静音图标	
【实际结果】	
4、页面中音量调节条左侧的图标变为非静音图标	
【复现率】	
3/3	

History

#1 - 2023-03-22 19:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189150	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-1a1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix volume icon is not mute icon after reboot.TC-RID: 1201-0201805IssueID: TS-R-BUG-117050Change-Id: Ifb9a171cab550f3e9f34f4cb9c2e7f1fba01769f			

#2 - 2023-03-22 19:24 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD Test赵飞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-22
- Root cause set to AOSP 原生问题。 AudioService 初始 mute 状态数据不正确。

■ Current conclusion

已处理，代码已入库。

■ My analysis

AOSP 原生问题。 AudioService 初始 mute 状态数据不正确。

■ Next action

测试验证。

#3 - 2023-03-23 14:07 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_MCE_FSE.M.R.user.01.00.0085.C101
验证结果：PASS

#4 - 2023-03-23 14:07 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files

图片.png	26 KB	2023-03-21	CD Test赵飞
--------	-------	------------	-----------