

Figure - Bug #117061

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【控制中心】【VC1】音乐播放器和亮度调节条尺寸不对

2023-03-21 15:10 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-21
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0084.C101(X
Need_Info:	TEST	Degrated:	--
Resolution:	INVALID	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		

Description			
【前提条件】			
1、设备正常启动			
【测试步骤】			
1.打开控制中心			
2、查看页面显示			
【预期结果】			
2、音乐播放器和亮度调节条的长度都等于两个组件的占位长度			
【实际结果】			
2、音乐播放器和亮度调节条尺寸不对 ‘			
【复现率】			
3/3			

History

- #1 - 2023-03-21 16:57 - CD FW 曹覃刚
- Status changed from New to NEED\_INFO
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- Need\_Info changed from -- to TEST

Hi, 永红

控制中心UI适配投入时间为03/21,请使用03/22的版本测试，十分感谢

- #2 - 2023-03-22 11:12 - CD TEST-方永红
- Status changed from NEED\_INFO to RESOLVED
- Resolution changed from -- to INVALID

3.22

不复现

#3 - 2023-03-22 11:12 - CD TEST-方永红  
- Status changed from RESOLVED to VERIFIED

#4 - 2023-03-22 11:12 - CD TEST-方永红  
- Status changed from VERIFIED to CLOSED

Files			
1509.png	319 KB	2023-03-21	CD TEST-方永红