

Figure - Bug #117112

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】【VC1】已连接的设备-与新设备配对-可用设备字体与ui不符

2023-03-23 16:16 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-23
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0085.C101(X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-24
Reproducibility:	Every time	Root cause:	非公共组件，UI 适配遗漏。
Test Type:	ST		

Description
【前提条件】 1、设备正常启动
【测试步骤】 1、进入设置 2、点击已连接的设备 3、点击与新设备配对 4、查看可用的设备字体
【预期结果】 4、可用设备字体与ui相符
【实际结果】 4、可用设备字体与ui不符
【复现率】 3/3

History

#1 - 2023-03-24 10:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189481	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Adapter available bluetooth devices category height and textsize.TC-RID: 1201-0201813IssueID: TS-R-BUG-117112Change-Id: Ic4ae6f0b76408b5c1097d347f5aa276030b83e69			

#2 - 2023-03-24 10:25 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-24
- Root cause set to 非公共组件, UI 适配遗漏。

■ Current conclusion

已处理，代码已入库。

■ My analysis

非公共组件，UI 适配遗漏。

■ Next action

测试验证。

#3 - 2023-03-27 15:58 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

【验证版本】FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102.202303260013

【验证情况】可用设备字体正常，与ui相符， pass

#4 - 2023-03-27 15:59 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

15.png	299 KB	2023-03-23	CDTS_Test 吴诗雨
--------	--------	------------	---------------