

Figure - Bug #117129

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】【VC1】应用-流量统计中应用图标与总计标题的距离过远与ui图不符合

2023-03-23 17:31 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-23
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0085
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-24
Reproducibility:	Every time	Root cause:	无标题分组元素占位导致。
Test Type:	ST		

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】	
1、进入设置-应用	
2、选择一个应用	
3、点击流量统计	
4、查看页面	
【预期结果】	
4、图标和总计标题的距离符合ui图	
【实际结果】	
4、图标和总计标题的距离比较远，看布局中间多了一个模块	
【复现率】	
3/3	

History

#1 - 2023-03-24 10:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189505	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Remove application data usage page empty view.TC-RID: 1201-0201813IssueID: TS-R-BUG-117129Change-Id: Ic7415e96138f1d375d2ff8d690072dff2a1091cf			

#2 - 2023-03-24 10:26 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CDTs_Test 吴诗雨

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-24
- Root cause set to 无标题分组元素占位导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

无标题分组元素占位导致。

■ Next action

测试验证。

#3 - 2023-03-28 10:13 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

【验证版本】FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086.C102

【验证情况】应用-流量统计中应用图标与总计标题的距离过远与ui图符合，pass

#4 - 2023-03-28 10:13 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
21.png	224 KB	2023-03-23	CDTS_Test 吴诗雨
21-1.png	126 KB	2023-03-23	CDTS_Test 吴诗雨
21-2.png	142 KB	2023-03-23	CDTS_Test 吴诗雨