

Figure - Bug #117130

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】【VC1】应用信息界面打开、卸载、强行停止的大小尺寸与ui不符

2023-03-23 17:36 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-23
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0085.C101(X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-24
Reproducibility:	Every time	Root cause:	VX1 和 VC1 设计稿不一致。
Test Type:	ST		

Description
【前提条件】 1、设备正常启动
【测试步骤】 1、进入应用 2、选择一个应用 3、查看页面情况，对比ui图
【预期结果】 3、应用信息界面打开、卸载、强行停止的大小尺寸与ui相符合
【实际结果】 3、应用信息界面打开、卸载、强行停止的大小尺寸与ui不符。ui图中的没有和字体对齐，要更里面一点。实际与字体对齐了
【复现率】 3/3

History

#1 - 2023-03-24 10:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189528	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settings: Adapter application detail action button style.TC-RID: 1201-0201813IssueID: TS-R-BUG-117130Change-Id: Ib477dd78313be3fd8a536aa6e713bba72db5c741			

#2 - 2023-03-24 10:28 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTs_Test 吴诗雨
- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-24
- Root cause set to VX1 和 VC1 设计稿不一致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

VX1 和 VC1 设计稿不一致。已和 UI 沟通，整体左右间距保持与 VX1 一致，已根据 UI 提供的新设计稿调整了。

■ Next action

测试验证。

#3 - 2023-03-28 10:27 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

- 【验证版本】FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086.C102
- 【验证情况】应用信息界面打开、卸载、强行停止的大小尺寸与ui符合， pass

#4 - 2023-03-28 10:27 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
20.png	236 KB	2023-03-23	CDTS_Test 吴诗雨