

Figure - Bug #117177

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【游戏模式】【VC1】在游戏页面下划打开通知中心，通知中心底部显示异常

2023-03-27 16:08 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-27
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Need_Info:		Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Severity:	Normal	Fixed Version:	2023-04-19
Reproducibility:	Every time	Root cause:	Bottom MaskView 初始化位置问题。
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开游戏模式			
2、打开游戏			
3、下划打开通知中心			
4、划到通知中心底部			
【预期结果】			
4、页面显示正常			
【实际结果】			
4、通知中心底部显示异常（见截图）			

History

- #1 - 2023-03-30 16:50 - CD FW 曹覃刚
- Status changed from New to NEED_INFO
 - Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
 - Need_Info changed from -- to TEST

Hi 永红

如飞书沟通，目前我们尝试了多个游戏，但是无法复现这个问题
请观察几个版本,猜测与具体游戏应用有关，复现时请记录好游戏名称和抓取日志，谢谢

- #2 - 2023-04-03 14:43 - CD TEST-方永红
- File 1439.txt added
 - File Phone-1A2212290000001651 2023-04-03 14-40-33.mp4 added
 - Status changed from NEED_INFO to ASSIGNED
 - Assignee changed from CD TEST-方永红 to CD FW 曹覃刚
 - Need_Info changed from TEST to --

你好，覃刚

目前在应用宝上复现该情况，后续也将持续关注其他游戏的通知中心显示问题

麻烦先基于日志和复现步骤分析问题

谢谢

#3 - 2023-04-03 19:54 - CD FW 曹覃刚

- Status changed from ASSIGNED to NEED_INFO
- Assignee changed from CD FW 曹覃刚 to CD TEST- 方永红
- Need_Info changed from -- to TEST

Hi 永红

尝试使用应用宝做类似操作，但是并未复现，这种UI类型的问题。

日志几乎没有参考意义

请帮忙再关注下，复现时的细节和步骤，非常感谢

#4 - 2023-04-14 17:34 - CD TEST-方永红

- File Phone-STS40X190078 2023-04-14 17-28-53.mp4 added
- Status changed from NEED_INFO to ASSIGNED
- Assignee changed from CD TEST- 方永红 to CD FW 曹覃刚
- Need_Info deleted (TEST)

- 【复现步骤】
- 1、恢复出厂设置
 - 2、安装应用宝
 - 3、使用应用宝下载应用
 - 4、等待下载几个应用
 - 5、打开通知中心
 - 6、显示异常

#5 - 2023-04-15 18:29 - CD FW 曹覃刚

- Assignee changed from CD FW 曹覃刚 to CD FW- 廖涛

#6 - 2023-04-19 14:24 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST- 方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-19
- Root cause set to Bottom MaskView 初始化位置问题。

■ Current conclusion

已处理，代码已入库。

■ My analysis

Bottom MaskView 初始化位置问题。

■ Next action

测试验证。

#7 - 2023-04-19 14:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194684	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Notification: Fix notification bottom mask view position problem.TC-RID: 1201-0201902IssueID: TS-R-BUG-117177Change-Id: I5460259b717352dc7af4c1b977f664977f5f5cb4			

#8 - 2023-04-21 19:04 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103).202304210449

4.21
验证通过

#9 - 2023-04-21 19:04 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1605.png	409 KB	2023-03-27	CD TEST-方永红
1439.txt	5.26 MB	2023-04-03	CD TEST-方永红
Phone-1A2212290000001651 2023-04-03 14-40-33.mp4	12.2 MB	2023-04-03	CD TEST-方永红
Phone-STS40X190078 2023-04-14 17-28-53.mp4	38.8 MB	2023-04-14	CD TEST-方永红