

Figure - Bug #117184

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【屏保】【VC1】设置-显示-屏保-当前的屏保-系统屏保页面与ui图不符

2023-03-27 17:03 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-27
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-03-31
Test Type:	ST	Root cause:	编码问题

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】	
1、进入设置-显示-屏保-当前的屏保-系统屏保	
2、查看当前页面，对比ui图	
3、查看屏保第五张图片与滚动条的距离	
【预期结果】	
2、系统屏保页面与ui图相符	
3、屏保第五张图片与滚动条的距离相符	
【实际结果】	
2、系统屏保页面与ui图不符，屏保图片的间距不对	
3、屏保第五张图片与滚动条的距离不符	

History

- #1 - 2023-03-30 19:34 - CD APP-王营
- Status changed from New to ASSIGNED
- % Done changed from 0 to 20
- #2 - 2023-03-31 10:53 - CD APP-王营
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP- 王营 to CDTs_Test 吴诗雨
- % Done changed from 20 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-31
- Root cause set to 编码问题

■ Current conclusion

问题已修复
VC1适配尺寸问题

■ Submit URL

<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+/191003>

#3 - 2023-04-01 16:06 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

【验证版本】FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102.202304010020

【验证情况】设置-显示-屏保-当前的屏保-系统屏保页面与ui图符合

#4 - 2023-04-01 16:06 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
3.png	509 KB	2023-03-27	CDTS_Test 吴诗雨
3-1.png	383 KB	2023-03-27	CDTS_Test 吴诗雨
3-2.png	388 KB	2023-03-27	CDTS_Test 吴诗雨