

Figure - Bug #117190

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【屏保】【VC1】自定义屏保选择图片页面，图片间隔、滚动条位置长度、字体大小间隔与ui图不符

2023-03-27 17:53 - CDTS_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-27
Priority:	Normal	Due date:	2023-04-03
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-05-06
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	ST		
Description			
【前提条件】			
1、设备正常启动			
2、有6个图片以上的相册			
【测试步骤】			
1、进入设置-显示-屏保-当前的屏保-自定义屏保-选择相册图片			
2、点击选择有6个图片以上的相册			
3、查看页面和滚动条位置以及下方文字位置，对于ui图			
【预期结果】			
3、图片间隔、滚动条位置长度、字体大小间隔与ui图相符			
【实际结果】			
3、图片间隔、滚动条位置长度、字体大小间隔与ui图不符			
Related issues:			
Related to Figure - Bug # 117189: 【AF】【EVT】【屏保】【VC1】自定义屏保...			
CLOSED2023-03-272023-04-03			

History

#1 - 2023-03-31 14:56 - CD APP-王营

- Due date set to 2023-04-03
- Status changed from New to ASSIGNED

#2 - 2023-04-07 16:21 - CD APP-王营

- % Done changed from 0 to 40

■ Current conclusion

问题已处理，待验证

■ My analysis

dimens文件适配UI尺寸有误差，已调整

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+/192318>

#3 - 2023-04-08 22:31 - CD APP-王营

- Status changed from ASSIGNED to RESOLVED
- % Done changed from 40 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-10
- Root cause set to 编码问题

#4 - 2023-04-27 20:05 - CD APP-王宏

■ Current conclusion

问题已处理，待验证

■ My analysis

recycler原生存在问题，已自定义滚动条解决

■ Submit URL

<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+/196914>

#5 - 2023-04-27 22:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196914	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:ScreenSaver:VC1 AdaptationTC-RID: 1201-0300604IssueID: TS-R-DF-117190Change-Id: Ie26e2c23fbe628725fa598cddb2ce3000ccceb6d			

#6 - 2023-05-05 17:24 - CD APP-王宏

- Assignee changed from CD APP-王营 to CDTS_Test 吴诗雨
- Fixed Version changed from 2023-04-10 to 2023-05-06

#7 - 2023-05-05 17:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197008	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:ScreenSaver:VC1 Adaptation1.Optimize custom screensaversTC-RID: 1201-0300604IssueID: TS-R-DF-117190Change-Id: I16334eeffe022f25ecbb8c759f8e122164eaf94c			

#8 - 2023-05-12 18:18 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

5.12

验证通过

#9 - 2023-05-12 18:18 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files				
8.png	329 KB	2023-03-27	CDTS_Test 吴诗雨	
8-1.png	261 KB	2023-03-27	CDTS_Test 吴诗雨	
8-2.png	337 KB	2023-03-27	CDTS_Test 吴诗雨	
8-3.png	590 KB	2023-03-27	CDTS_Test 吴诗雨	