

Figure - Bug #117221

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT】【桌面】adb reboot重启设备后dock栏应用不在显示dock栏，桌面没有在第一页，在最后一页

2023-03-28 18:05 - 物联网测试组_CDTS 唐霞

Status:	CLOSED	Start date:	2023-03-28
Priority:	Normal	Due date:	2023-04-03
Assignee:	物联网测试组_CDTS 唐霞	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086C102(X
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-04-05
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	Release Test		
Description			
【前提条件】 已安装应用超过3屏			
【测试步骤】 1.在dock栏添加应用【微信】【肯德基】【QQ音乐】【设置】 2.adb reboot重启设备			
【预期结果】 dock栏应用显示正确，launcher显示首屏			
【测试结果】 dock栏应用只显示【QQ音乐】【设置】，launcher显示最后一屏			

History

#1 - 2023-03-28 19:55 - 物联网测试组_CDTS 唐霞

断电重启也存在这种现象

#2 - 2023-03-29 15:19 - CD APP-王营

- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营 to CD APP-王宏

#3 - 2023-03-31 14:41 - CD APP-王营

- Due date set to 2023-04-03

#4 - 2023-04-04 11:01 - CD APP-王宏

- % Done changed from 0 to 50

■ Current conclusion

已提交

■ My analysis

未正确触发hotseat保存到数据库的操作,修改逻辑使正确触发保存操作

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/191733>

#5 - 2023-04-04 16:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
191733	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Hotseat bug fixed1.fixed issue 117218 1172212.The icon in hotspot has not been restored to its original state after restartingTC-RID: 0301-0205303IssueID: TS-R-BUG-117221Change-Id: Id7a2fa0d1bef6e1500a99740a2ee6fade78a62a2			

#6 - 2023-04-04 16:48 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to 物联网测试组_CDTS 唐霞
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-04-05
- Root cause set to 编码问题

#7 - 2023-04-10 19:51 - 物联网测试组_CDTS 唐霞

- Status changed from RESOLVED to VERIFIED

验证通过，关闭问题单

验证版本：FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103.202304100016.zip

#8 - 2023-04-10 19:53 - 物联网测试组_CDTS 唐霞

- Status changed from VERIFIED to CLOSED

#9 - 2023-07-10 11:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213303	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
Revert AF:Launcher:Fixed cellYFromOrder in hotseatTC-RID: 0301-0205303IssueID: TS-R-BUG-117221This reverts commit 8d81c9fa648d1594b11685783d91f39b08033ccf.Reason for revert: <not fixed>Change-Id: lee8261e97e8239ac6a90ab94ba4f7807a1f9cc7d			

#10 - 2023-07-10 11:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213331	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com

AF:Launcher:icon dismiss when exit folder in hotseatTC-RID: 0301-0205303IssueID: TS-R-BUG-117221,IOVDEV-37540Change-Id: I0e538701a0660a1e73b7937e7c0350110bf44da1

#11 - 2023-07-10 11:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213302	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
Revert AF:Launcher:Hotseat bug fixedTC-RID: 0301-0205303IssueID: TS-R-BUG-117221This reverts commit fbe3e3212cde000eca26a8bf62a31738f14ed481.Reason for revert: <not fixed>Change-Id: I2a530b8540606403a1411b05178c300178f28d1e			

#12 - 2023-07-11 15:08 - CDTS_Test 吴诗雨

0711DB验证通过

#13 - 2023-07-11 21:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213990	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert AF:Launcher:Hotseat bug fixedTC-RID: 0301-0205303IssueID: TS-R-BUG-117221This reverts commit fbe3e3212cde000eca26a8bf62a31738f14ed481.Reason for revert: <not fixed>Change-Id: I2a530b8540606403a1411b05178c300178f28d1e(cherry picked from commit f460dfc2892cf25de35ab97929c6f553d4580dd7)			

#14 - 2023-07-11 21:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213991	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert AF:Launcher:Fixed cellYFromOrder in hotseatTC-RID: 0301-0205303IssueID: TS-R-BUG-117221This reverts commit 8d81c9fa648d1594b11685783d91f39b08033ccf.Reason for revert: <not fixed>Change-Id: Iee8261e97e8239ac6a90ab94ba4f7807a1f9cc7d(cherry picked from			

#15 - 2023-07-11 21:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213992	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Launcher:icon dismiss when exit folder in hotseatTC-RID: 0301-0205303IssueID: TS-R-BUG-117221,IOVDEV-37540Change-Id: I0e538701a0660a1e73b7937e7c0350110bf44da1(cherry picked from commit 477fe48ddb43b551d7e0318b9edb88e89ac1a3b)			

Files

328-2.txt	2.33 MB	2023-03-28	物联网测试组_CDTS 唐霞
-----------	---------	------------	----------------