

Figure - Bug #117233

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT】【控制中心】游戏中未开启消息弹窗收到消息后在开启消息弹窗，在桌面/游戏中，收到通知消息，弹窗消息消失后，页面显示异常

2023-03-29 16:53 - 物联网测试组_CDTS 唐霞

Status:	CLOSED	Start date:	2023-03-29
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-31
Reproducibility:	Frequently	Root cause:	通知中心未展开时，不应该绘制滚动条和遮罩层
Test Type:	Release Test		

Description	
【测试步骤】 1.打开游戏模式，进入游戏中收到通知消息，通知消息消失后 2.展开工具箱开启弹窗消息 【预期结果】 收到消息后显示正确 【测试结果】 在桌面/游戏中，收到通知消息，弹窗消息消失后，页面显示异常	

History

#1 - 2023-03-30 16:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
190985	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Scrollbars and mask layers should not be drawn in the non-expanded stateTC-RID: 1201-0201902IssueID: TS-R-BUG-117233Change-Id: I9999a62affa49e05807c580ca31c20af5ba2e6ba			

#2 - 2023-03-30 16:04 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to 物联网测试组_CDTS 唐霞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-31
- Root cause set to 通知中心未展开时，不应该绘制滚动条和遮罩层

#3 - 2023-03-31 16:51 - 物联网测试组_CDTS 唐霞

- Status changed from RESOLVED to VERIFIED

验证通过，验证版本：FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102.202303310316

#4 - 2023-03-31 16:51 - 物联网测试组_CDTS 唐霞
- Status changed from VERIFIED to CLOSED

验证通过，关闭问题单

Files			
通知消失后显示异常.mp4	1.77 MB	2023-03-29	物联网测试组_CDTS 唐霞