

Figure - Bug #117244

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】设置-显示，调节亮度为最低，底框没有框住小太阳图标

2023-03-30 10:58 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-03-30
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086.C102(X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-30
Reproducibility:	Every time	Root cause:	SeekBar 背景切图问题。
Test Type:	ST		

Description	
【前提条件】	
1、设备正常启动	
【测试步骤】)	
1、进入设置-显示-亮度	
2、调节亮度为最低	
3、查看底框范围	
【预期结果】	
3、底框范围与亮起的时候相同，能框住小太阳	
【实际结果】	
3、底框比亮起的时候范围要小，没有框住小太阳，只有小太阳的一半 (用投屏软件可以更清楚的看到，详细情况看截图)	
【复现率】	
3/3	

History

#1 - 2023-03-30 16:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
190979	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF: SystemUI: Fix brightness seekbar background problem.TC-RID: 1201-0201903IssueID: TS-R-BUG-117244Change-Id: Ida589097ea136491b6d50f11dcb7b53bc44c3ef4			

#2 - 2023-03-30 16:06 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CDTs_Test 吴诗雨

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-30
- Root cause set to SeekBar 背景切图问题。

■ Current conclusion

已处理，代码已入库。

■ My analysis

SeekBar 背景切图问题。

■ Next action

测试验证。

#3 - 2023-03-31 14:07 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

【验证版本】FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102.202303310316

【验证情况】设置-显示，调节亮度为最低，底框框住小太阳图标，pass

#4 - 2023-03-31 14:07 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
screenshot-20230330-105148.png	189 KB	2023-03-30	CDTS_Test 吴诗雨
screenshot-20230330-105304.png	188 KB	2023-03-30	CDTS_Test 吴诗雨