

Figure - Bug #117245

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【控制中心】【VC1】音乐播放器按钮及音、亮调节条的图标大小与UI设计不一致

2023-03-30 11:11 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-30
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0088
Severity:	Normal	Fixed Version:	2023-04-04
Reproducibility:	Every time	Root cause:	已更新图片资源
Test Type:	ST		
Description			
【前提条件】 设备已开机			
【测试步骤】 1、打开控制中心			
【预期结果】 1、控制中心各图标大小与UI设计一致			
【实际结果】 1、音乐播放器按钮及音、亮调节条的图标大小与UI设计不一致			

History

#1 - 2023-04-03 15:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
191587	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: update some image resourcesTC-RID: 1201-0201903IssueID: TS-R-BUG-117245Change-Id: I8c3f16e2aa38067d8e96bf597c081968ac35c1e4			

#2 - 2023-04-03 15:31 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚到 CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-04
- Root cause set to 已更新图片资源

#3 - 2023-04-04 10:34 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0088.C102(X102)

4.4
验证通过

#4 - 2023-04-04 10:34 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1058.png	104 KB	2023-03-30	CD TEST-方永红