

Figure - Bug #117259

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【游戏模式】【VC1&VX1】弹幕通知框尺寸和位置与UI设计有差异

2023-03-30 15:14 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-30
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086.C102(X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-03-31
Reproducibility:	Every time	Root cause:	UI样式问题
Test Type:	ST		

Description	
【前提条件】	
1、设备已开机	
【测试步骤】	
1、打开游戏模式	
2、打开游戏	
3、打开消息弹幕	
4、设备收到飞书or微信消息	
5、查看弹幕显示	
【预期结果】	
5、消息弹幕框框尺寸和位置与UI设计一致	
【实际结果】	
5、弹幕通知框尺寸和位置与UI设计有差异	

History

#1 - 2023-03-30 15:54 - CD FW-程天颖

- Status changed from New to ASSIGNED

#2 - 2023-03-31 15:27 - CD FW-程天颖

■ Current conclusion

bug已解决,代码已提交

■ My analysis

样式错误

■ Next action

代码入库

#3 - 2023-03-31 15:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
191295	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	tianying.cheng@thundersoft.com

	m/apps/GameMode	-dev	
AF:GameMode: Fixed bullet screen UITC-RID: 1201-0204808IssueID: TS-R-BUG-117259Change-Id: I6927f4f855d1ba0105c2be545c99224e217f19d5			

#4 - 2023-03-31 15:41 - CD FW-程天颖

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-程天颖 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-03-31
- Root cause set to UI样式问题

■ Current conclusion

bug已解决,代码已入库

■ My analysis

样式错误

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/GameMode/+191295>

#5 - 2023-04-03 19:32 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

4.3

验证通过

#6 - 2023-04-03 19:32 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

游戏弹幕-VX1.png	381 KB	2023-03-30	CD TEST-方永红
游戏弹幕.png	276 KB	2023-03-30	CD TEST-方永红