

Figure - Bug #117274

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT】【控制中心】开关控制中心的快捷功能组件，组件周围会短暂出现白边

2023-03-31 10:20 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-03-31
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0086C102(X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0088C102(X
Severity:	Normal	Fixed Version:	2023-04-03
Reproducibility:	Every time	Root cause:	删除组件点击时的水波纹效果
Test Type:	ST		
Description			
【前提条件】			
1、设备正常启动			
【测试步骤】（以蓝牙为例）			
1、打开控制中心			
2、点击蓝牙组件			
【预期结果】			
2、正常开关蓝牙，且页面显示正常			
【实际结果】			
2、组件周围会短暂出现白边			

History

#1 - 2023-03-31 16:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
191340	general/platform/frameworks/base	Pre_figure_turbox-c2130c-1a1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Remove the water ripple effect when the control center component is clickedTC-RID: 1201-0201903IssueID: TS-R-BUG-117274Change-Id: If4677cd36dd1190b0b810f426681eda4d7670ab8			

#2 - 2023-03-31 16:58 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-03
- Root cause set to 删除组件点击时的水波纹效果

#3 - 2023-04-04 10:04 - CD FW 曹覃刚
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红

#4 - 2023-04-04 10:35 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0088.C102(X102)

4.4
验证通过

#5 - 2023-04-04 10:35 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-1A2212290000001651 2023-03-31 10-16-08.mp4	17.7 MB	2023-03-31	CD TEST-方永红