

Figure - Bug #117283

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT】【桌面】长按应用，点击应用信息，跳转到设置的网络和互联网界面

2023-03-31 15:25 - CDTS\_Test 吴诗雨

|                  |               |                   |                                                |
|------------------|---------------|-------------------|------------------------------------------------|
| Status:          | CLOSED        | Start date:       | 2023-03-31                                     |
| Priority:        | Normal        | Due date:         | 2023-04-03                                     |
| Assignee:        | CDTS_Test 吴诗雨 | % Done:           | 100%                                           |
| Category:        | CD-FW         | Estimated time:   | 0.00 hour                                      |
| Target version:  |               |                   |                                                |
| Need_Info:       | --            | Found Version:    | FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102) |
| Resolution:      | FIXED         | Degrated:         | No                                             |
| Severity:        | Normal        | Verified Version: |                                                |
| Reproducibility: | Every time    | Fixed Version:    | 2023-04-03                                     |
| Test Type:       | ST            | Root cause:       | 应用详情页面异常情况处理保护修改引发。                            |

Description

【前提条件】

1、设备正常启动

【测试步骤】

- 1、长按应用
- 2、点击应用信息
- 3、观察页面跳转

【预期结果】

3、页面内容正常显示

【实际结果】

3、跳转到设置的网络和互联网界面

【复现率】

3/3

History

#1 - 2023-03-31 15:47 - CD FW 曹覃刚

- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#2 - 2023-03-31 19:30 - CD FW-廖涛

- Due date set to 2023-04-03
- % Done changed from 0 to 80
- Root cause set to 应用详情页面异常情况处理保护修改引发。

■ Current conclusion

已修复，代码已提交。

■ My analysis

应用详情页面异常情况处理保护修改引发。

■ Next action  
代码 Review 入库。

#3 - 2023-04-03 10:23 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                           | Project                                     | Branch                                        | Uploader                 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------|--------------------------|
| 191410                                                                                                                                                       | general/platform/packages/apps/Settin<br>gs | Pre_figure_turbox-c2130c-la1.1-qssi12<br>-dev | tao.liao@thundersoft.com |
| AF:Settings: Fix navigate to settings from outside problem.TC-RID: 1201-0201813IssueID: TS-R-BUG-117283Change-Id: I736597cabcd10cd48eee00dd957208aee3012885e |                                             |                                               |                          |

#4 - 2023-04-03 10:24 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS\_Test 吴诗雨
- % Done changed from 80 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-03

■ Current conclusion  
已处理，代码已入库。

■ My analysis  
--

■ Next action  
测试验证。

#5 - 2023-04-04 10:15 - CDTS\_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild\_HH\_MCE\_FSE.M.R.user.01.00.0088.C102  
验证情况：长按应用，点击应用信息，正常跳转

#6 - 2023-04-04 10:15 - CDTS\_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

| Files               |         |            |               |
|---------------------|---------|------------|---------------|
| 20230331-152229.mp4 | 3.15 MB | 2023-03-31 | CDTS_Test 吴诗雨 |