

Figure - Bug #117308

测试 Test-ST # 111337 (New): ST测试总票
测试 Test-ST # 116840 (New): 中控联调测试-AF

【AF】【EVT3】【遥控器】副屏遥控器打开后副屏重启，中控侧滑动副屏触摸板时副屏没有鼠标指针

2023-04-03 16:12 - CD Test赵飞

Status:	CLOSED	Start date:	2023-04-03
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-04-03
Reproducibility:	Every time	Root cause:	重连之后中控遥控器没有创建鼠标设备
Test Type:	ST		

Description
【前提条件】 1、副屏与中控已连接 【测试步骤】 1、中控打开遥控器应用 2、副屏断电再上电 3、中控侧遥控器切换到“副屏触摸板” 【预期结果】 5、副屏上出现鼠标指针 【实际结果】 5、副屏上没有鼠标指针

History

#1 - 2023-04-03 17:24 - CD FW-程天颖

- Status changed from New to ASSIGNED

- Root cause set to 重连之后中控遥控器没有创建鼠标设备

#2 - 2023-04-03 19:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
191624	general/platform/vendor/thundercom/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Fixed When restart have no mouse pointTC-RID: 1201-0206001IssueID: TS-R-BUG-117308Change-Id: I115cbc0c4f22e3398004fe10be3491574c79ce17			

#3 - 2023-04-03 19:40 - CD FW-程天颖

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD FW-程天颖 to CD Test赵飞

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degraded changed from -- to No
- Fixed Version set to 2023-04-03

■ Current conclusion

bug已解决,提交已入库

■ My analysis

中控创建虚拟鼠标设备的时机问题,副屏重启后没有再次创建虚拟鼠标设备,现在对sdk的创建虚拟鼠标设备功能进行了回收,由服务端统一创建和销毁

■ Submit URL

<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/thundercomm/apps/RemoteControlServer/+/191624>

#4 - 2023-04-04 10:32 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本 : FlatBuild_HH_MCE_FSE.M.R.user.01.00.0088.C102

验证结果 : PASS

#5 - 2023-04-04 10:32 - CD Test赵飞

- Status changed from VERIFIED to CLOSED