

Figure - Bug #117364

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】部分页面仍有 “ 平板电脑，手机 ” 等字样

2023-04-07 17:38 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-07
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0089
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0090
Severity:	Normal	Fixed Version:	2023-04-10
Reproducibility:	Every time	Root cause:	文案处理遗漏。
Test Type:	ST		
Description			
【相关页面】			
1、应用宝的安装权限弹窗			
2、点击应用宝的安装弹窗点击设置之后的页面			
3、设置-关于本机-修改设备名称之后产生的确认弹窗			
【预期结果】			
显示为 “ 设备或者高合娱乐副屏 ”			

History

#1 - 2023-04-07 17:42 - CD FW-廖涛

- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#2 - 2023-04-10 10:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
192483	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settings: Fix device name.TC-RID: 1201-0201813IssueID: TS-R-BUG-117364Change-Id: I598f5482a0c69044664e4f2c49b0eaf1f29b36d8			

#3 - 2023-04-10 10:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
192481	general/platform/packages/apps/Settin	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
gs			
AF:Settings: Fix device name.TC-RID: 1201-0201813IssueID: TS-R-BUG-117364Change-Id: I44cb6de2b710b847421d1784a61f40b736756672			

#4 - 2023-04-10 10:23 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-10
- Root cause set to 文案处理遗漏。

■ Current conclusion

已处理，代码已入库。

■ My analysis

文案处理遗漏。

■ Next action

测试验证。

#5 - 2023-04-11 13:40 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0090.C103(X103)

4.11

验证通过

#6 - 2023-04-11 13:40 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#7 - 2023-04-12 13:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193179	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Modify tablet name.TC-RID: 1201-0201813IssueID: TS-R-BUG-117364Change-Id: lfd04f2d07e6e61ed8696f5d6813ccd55cb3d5b00			

Files			
1729.png	107 KB	2023-04-07	CD TEST-方永红
17362.png	111 KB	2023-04-07	CD TEST-方永红
1732.jpg	145 KB	2023-04-07	CD TEST-方永红