

Status:	CLOSED	Start date:	2023-04-14
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	AUDIO-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	中控版本：03.02.0062.C101副屏版本：0090
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Reproducibility:	Every time	Fixed Version:	2023-04-20
Test Type:	ST	Root cause:	由于当前副屏不能给中控发送mute_on，所以优化

Description
【前提条件】 实车341 【操作步骤】 1.点击打开虎牙直播 【实际结果】 整车自动静音 【期望结果】 正常进入虎牙app，无其他异常 【时间】 4月1号 17:36 【备注】 VIN:LJD8BB3F0P0000341 LOG已经上传云 EE环境

History

- #1 - 2023-04-14 16:28 - CD FW 曹覃刚
- Category changed from CD-FW to AUDIO-FW
- Assignee changed from CD FW 曹覃刚 to Multimedia组-RD3_TSCD 梁卿山

Hi 卿山

此问题是Audio类问题，请帮忙分析

- #2 - 2023-04-15 12:32 - Multimedia组-RD3_TSCD 梁卿山
- Status changed from New to ASSIGNED

Hi ALL

■ 当前分析

04-10 01:39:34.854 17595 17595 W com.duowan.kiw: Accessing hidden field Ljava/util/Collections\$SynchronizedCollection;->mutex:Ljava/lang/Object; (max-target-o, reflection, denied)

04-10 01:39:37.561 17595 17595 W AudioManager: setStreamMute is deprecated. adjustStreamVolume should be used instead.

04-10 01:39:37.562 994 11103 D AudioIDCMicroNegotiator: idcm_volume:setIDCMicroAudioMute

04-10 01:39:37.562 994 11103 D AudioIDCMicroNegotiator: idcm_common:requestResult method = setMute parameters = {"functionInfo":{"IDCM_VolumeMute_Media":"mute_on"}}

04-10 01:39:37.634 2146 18490 I MicroService: onResponse(setMute): {"functionInfo":{"IDCM_VolumeMute_Media":"mute_on"}}

根据以上日志

当前分析，虎牙APP在打开时会主动调用setstreammute静音当前流。

由于当前副屏不能给中控发送mute_on,但是该接口中控是否需要对应处理，还需要和中控讨论。

#3 - 2023-04-18 14:53 - Multimedia组-RD3_TSCD 梁卿山

- Status changed from ASSIGNED to NEED_INFO
- Assignee changed from Multimedia组-RD3_TSCD 梁卿山 to CD TEST-方永红
- Degrated changed from -- to No

HI 永红

当前内部可以处理，提交已经生成，开飞自测OK，请测试帮忙验证，谢谢

提交

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+/194212>

VB地址：

Figure/VerifyBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/20230417/202304171649-385

#4 - 2023-04-20 16:06 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
194212	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: SetStreamMute do not syncSetStreamMute do not syncTC-RID: 0301-0900116IssueID: TS-R-BUG-117482Change-Id: Idc49f0dda5255b5cd7ad8aa17ee54f6e2c4442ea			

#5 - 2023-04-20 16:09 - Multimedia组-RD3_TSCD 梁卿山

- Resolution changed from -- to FIXED
- Fixed Version set to 2023-04-20
- Root cause set to 由于当前副屏不能给中控发送mute_on, 所以优化了这部分。

Hi 永红

该提交已经合并，请使用4/20后的版本验证，谢谢！

#6 - 2023-04-20 18:52 - CD TEST-方永红

- Status changed from NEED_INFO to RESOLVED

#7 - 2023-04-21 11:36 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- % Done changed from 0 to 100

- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103).202304210449

4.21

验证通过

#8 - 2023-04-21 11:37 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

虎牙导致静音.mp4	4.31 MB	2023-04-14	物联网测试组_TSCD 王维
------------	---------	------------	----------------