

Figure - Bug #117515

【IOVDEV-20102】 【内部】 【VC1】 【0066】 【台架/EE环境】 【HRYTTESTVINMGM328】 【副屏遥控器】

副屏部分图标按键的焦点不显示

2023-04-14 16:36 - 物联网测试组_TSCD 王维

Status:	CLOSED	Start date:	2023-04-14
Priority:	Normal	Due date:	
Assignee:	物联网测试组_TSCD 王维	% Done:	100%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:		Found Version:	中控版本：03.02.0066.C101副屏版本：0086
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-04-18
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	ST		

Description
【前提条件】 1、车机已上电，网络正常 2、台架处于测试环境 【操作手順】 1、进入副屏遥控器应用，位于按键显示页面 2、移动焦点到最右边最上面相册图标 3、点击遥控器下键 【实际结果】 3、音乐图标的焦点消失 （点击欧克键可以进入音乐界面） 【期望结果】 3、焦点移动到 音乐图标 测试时间：20230403 13：22 副屏遥控器 apk版本：3.0.15.66 副屏版本：86 usedebug版本 副屏和主屏的日志请见附件，测试视频请见附件

History

- #1 - 2023-04-14 16:44 - CD FW-程天颖
- Status changed from New to ASSIGNED
- Assignee changed from CD FW-程天颖 to CD APP-王营

launcher方向控制适配问题，帮忙分析一下，谢谢

- #2 - 2023-04-14 17:19 - CD FW 曹覃刚
- Category changed from CD-FW to CD-APP

- #3 - 2023-04-14 18:06 - CD APP-王营
- Assignee changed from CD APP-王营 to CD APP-王宏

#4 - 2023-04-17 20:18 - CD APP-王宏

- % Done changed from 0 to 50

■ Current conclusion

已提交

■ My analysis

hotseat中焦点背景被hotseatBg给盖住了（DragLayer上绘制的背景），解决方案是直接在hotseat中绘制出背景

■Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/194342>

#5 - 2023-04-17 20:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194342	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Focus drawing issue under remote controlTC-RID: 0301-0205303IssueID: TS-R-BUG-117515Change-Id: I2f23a84d8518e9c018680f1b7d69f3ff8eed4078			

#6 - 2023-04-17 20:37 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to 物联网测试组_TSCD 王维
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-04-18
- Root cause set to 编码问题

#7 - 2023-04-19 17:38 - 物联网测试组_TSCD 王维

- Category changed from CD-APP to 依赖客户及其供应商解决
- Status changed from RESOLVED to VERIFIED

待客户验证

#8 - 2023-04-21 14:22 - 物联网测试组_TSCD 王维

- Status changed from VERIFIED to VERIFY_FAILED

#9 - 2023-04-21 14:22 - 物联网测试组_TSCD 王维

- Status changed from VERIFY_FAILED to RESOLVED

#10 - 2023-04-21 14:22 - 物联网测试组_TSCD 王维

- Status changed from RESOLVED to NEED_INFO

#11 - 2023-05-05 11:42 - CDTs_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

客户验证通过

#12 - 2023-05-05 11:42 - CDTs_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

#13 - 2023-05-05 11:42 - CDTs_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

Files			
13-22.mp4等.zip	7.33 MB	2023-04-14	物联网测试组_TSCD 王维