

Figure - Bug #117541

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111049 (New): AF-V2.0-副屏遥控器

【AF】【EVT3】【遥控器】设备1在被顶掉控制权后，再次点击连接，无法夺回控制权

2023-04-17 20:02 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-17
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0094.C103(X103)
Reproducibility:	Every time	Fixed Version:	2023-04-18
Test Type:	ST	Root cause:	遥控器不能在连接的时候夺取控制权引起的

Description	
【前提条件】	
1、两个手机、副屏处于同一局域网下	
【测试步骤】	
1、手机1连接遥控器	
2、手机2连接遥控器	
3、在手机1上点击连接	
4、手机1上使用遥控器	
【预期结果】	
2、可正常使用	
4、可正常使用	
【实际结果】	
2、可正常使用	
4、不可使用	

History

#1 - 2023-04-17 20:03 - CD TEST-方永红

ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_117541

#2 - 2023-04-17 20:15 - CD TEST-方永红

- Subject changed from 【AF】【EVT3】【遥控器】设备1再被顶掉控制权后，再次点击连接，无法夺回控制权to 【AF】【EVT3】【遥控器】设备1在被顶掉控制权后，再次点击连接，无法夺回控制权

#3 - 2023-04-18 10:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194350	general/platform/vendor/thundercom m/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

AF:RemoteControl: Client(iOS) - Fixed Control permissionTC-RID: 1201-0206003IssueID: TS-R-BUG-117541Change-Id: I6996d3e2e3c048a9a76d11a9e0b8bfd16349f41a

#4 - 2023-04-18 14:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194341	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Server - Fixed Control permissionTC-RID: 1201-0206001IssueID: TS-R-BUG-117541Change-Id: If96ed6242ac48c0e6d72175431e48157ac3d0732			

#5 - 2023-04-18 14:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194348	general/platform/vendor/thundercomm/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Fixed Control permissionTC-RID: 1201-0206003IssueID: TS-R-BUG-117541Change-Id: Id744a29aaebf39273163c1b61a546b7af68a059c			

#6 - 2023-04-18 15:22 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CD TEST-方永红

- Current conclusion
bug已解决，提交已入库
- My analysis
遥控器不能在连接的时候夺取控制权引起的
- Submit URL
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlClients/+/194350>
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlServer/+/194341>
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlClients/+/194348>

#7 - 2023-04-18 15:23 - CD FW-程天颖
- Status changed from New to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-04-18
- Root cause set to 遥控器不能在连接的时候夺取控制权引起的

#8 - 2023-04-25 17:55 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0094.C103(X103)

4.25

验证通过

#9 - 2023-04-25 17:56 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED