

Figure - Bug #117565

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【控制中心】【VX1】在控制中心点击“设置中心”不是进入控制中心编辑页，使用体验不好

2023-04-19 15:04 - 物联网测试组_CDTS 唐霞

Status:	CLOSED	Start date:	2023-04-19
Priority:	High	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C108(X103)
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【测试步骤】 菜单栏下拉进入控制中心，点击“设置中心” 【预期结果】 进入 控制中心编辑页 【测试结果】 1、没有进入控制中心编辑页，进入的是setting页 2、控制中心的编辑按钮在右上角，无文字描述 3、结合以上描述，使用体验不好，“设置中心”描述对使用者有误导			

History

#1 - 2023-04-19 15:25 - 物联网测试组_CDTS 唐霞

- Status changed from New to RESOLVED

提错了，非问题关闭问题单

#2 - 2023-04-19 15:25 - 物联网测试组_CDTS 唐霞

- Status changed from RESOLVED to VERIFIED

#3 - 2023-04-19 15:25 - 物联网测试组_CDTS 唐霞

- Status changed from VERIFIED to CLOSED

#4 - 2023-04-19 15:31 - CDTS_TEST 王成

- Subject changed from 【AF】【EVT】【控制中心】【VX1】在控制中心点击“设置中心”不能进入控制中心编辑页 to 【AF】【EVT】【控制中心】【VX1】在控制中心点击“设置中心”不是进入控制中心编辑页，使用体验不好

- Description updated

- Status changed from CLOSED to New

- Assignee changed from CD FW 曹覃刚 to 方案组-RD3_CDTS 王浩云

#5 - 2023-04-19 15:39 - 方案组-RD3_CDTS 王浩云

- Assignee changed from 方案组-RD3_CDTS 王浩云 to CDTS_TEST 王成

不予解决，请对方测试，仔细查看PRD，UX文档的定义，若要修改需求，请对方产品邮件输入

#6 - 2023-04-19 16:14 - CDTS_TEST 王成

- Status changed from New to RESOLVED

#7 - 2023-04-19 16:14 - CDTS_TEST 王成

- Status changed from RESOLVED to VERIFIED

#8 - 2023-04-19 16:14 - CDTS_TEST 王成

- Status changed from VERIFIED to CLOSED

Files

不能进入设置中心.mp4	814 KB	2023-04-19	物联网测试组_CDTS 唐霞
--------------	--------	------------	----------------