

Figure - Bug #117574

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】 【EVT3】 【小窗模式】 强制小窗应用打开后，再次点击桌面上的该应用图标，图标无放大动效

2023-04-19 17:02 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-19
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Severity:	Normal	Fixed Version:	2023-04-21
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	ST		

Description	
【测试步骤】	
1.打开一个强制小窗应用	
2、再次点击桌面上的该应用图标	
【预期结果】	
2、点击图标时有点击效果	
已打开的小窗状态合页面显示不发生改变	
【实际结果】	
1、图标无点击动效	

History

#1 - 2023-04-19 18:14 - CD APP-王宏

- % Done changed from 0 to 50

- Root cause set to 编码问题

Current conclusion

已提交

My analysis

修改小窗启动时未注意到图标的动画问题,现已修改

Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/194798>

#2 - 2023-04-20 09:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194798	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Launcher:Small window startup icon animationTC-RID: 0301-0205301IssueID: TS-R-BUG-117574Change-Id: Ie9b1134e7c59a83277bfef95b2fc1aad53534826			

#3 - 2023-04-20 09:59 - CD APP-王宏

- Status changed from New to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-04-21

#4 - 2023-04-21 11:32 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103).202304210449

4.21
验证通过

#5 - 2023-04-21 11:33 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190078 2023-04-19 16-52-53.mp4	4.31 MB	2023-04-19	CD TEST-方永红