

Figure - Bug #117584

测试 Test-ST # 113421 (New): V4.0功能与专项测试

测试 Test-ST # 113422 (New): V4.0专项--AF专项--monkey测试

【AF】【EVT3】【Monkey】Monkey测试24小时，出现CRASH: com.android.systemui (2)

2023-04-20 10:23 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-20
Priority:	Urgent	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0095.C103(X103)
Severity:	Critical	Fixed Version:	2023-04-24
Reproducibility:	Occasionally	Root cause:	默认资源未定义，已添加默认资源
Test Type:	Monkey Test		
Description			
【执行命令】 adb shell monkey --pkg-blacklist-file /sdcard/blacklist.txt --ignore-crashes --ignore-timeouts --ignore-security-exceptions --monitor-native-crashes --ignore-native-crashes -s 20 --throttle 500 --pct-touch 30 --pct-motion 15 --pct-nav 15 --pct-majornav 15 --pct-syskeys 5 --pct-appswitch 10 --pct-anyevent 10 --ignore-crashes -v -v 172800 2>/sdcard/error.txt 1>/sdcard/info.txt 【错误信息】 CRASH: com.android.systemui (pid 2016) // Short Msg: java.lang.UnsupportedOperationException // Long Msg: java.lang.UnsupportedOperationException: Can't convert value at index 6 to dimension: type=0x1 // Build Label: TC/figure_CN/figure:12/SKQ1.220201.001/2922:user/test-keys // Build Changelist: 2922 // Build Time: 1681840562000 // java.lang.RuntimeException: Unable to start activity ComponentInfo{com.android.systemui/com.android.systemui.settings.brightness.BrightnessDialog}: android.view.InflateException: Binary XML file line #25 in com.android.systemui:layout/quick_settings_brightness_dialog: Binary XML file line #25 in com.android.systemui:layout/quick_settings_brightness_dialog: Error inflating class <unknown> // at android.app.ActivityThread.performLaunchActivity(ActivityThread.java:3636) // at android.app.ActivityThread.handleLaunchActivity(ActivityThread.java:3793) // at android.app.servertransaction.LaunchActivityItem.execute(LaunchActivityItem.java:103) // at android.app.servertransaction.TransactionExecutor.executeCallbacks(TransactionExecutor.java:135) // at android.app.servertransaction.TransactionExecutor.execute(TransactionExecutor.java:95) // at android.app.ActivityThread\$H.handleMessage(ActivityThread.java:2211) // at android.os.Handler.dispatchMessage(Handler.java:106) // at android.os.Looper.loopOnce(Looper.java:201) // at android.os.Looper.loop(Looper.java:288) // at android.app.ActivityThread.main(ActivityThread.java:7880) // at java.lang.reflect.Method.invoke(Native Method) // at com.android.internal.os.RuntimeInit\$MethodAndArgsCaller.run(RuntimeInit.java:548) // at com.android.internal.os.ZygoteInit.main(ZygoteInit.java:1009) // Caused by: android.view.InflateException: Binary XML file line #25 in com.android.systemui:layout/quick_settings_brightness_dialog: Binary XML file line #25 in com.android.systemui:layout/quick_settings_brightness_dialog: Error inflating class <unknown> // Caused by: android.view.InflateException: Binary XML file line #25 in com.android.systemui:layout/quick_settings_brightness_dialog: Error inflating class <unknown> // Caused by: java.lang.reflect.InvocationTargetException			

History

- #1 - 2023-04-20 10:31 - CD APP-王营
- Category changed from CD-APP to CD-FW
 - Status changed from New to ASSIGNED
 - Assignee changed from CD APP-王营 to CD FW 曹覃刚
- #2 - 2023-04-20 18:03 - CD FW 曹覃刚
- Status changed from ASSIGNED to RESOLVED
 - Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Fixed Version set to 2023-04-21
 - Root cause set to 与#117573 原因一致，已修复
- #3 - 2023-04-23 10:26 - CD TEST-方永红
- File error.txt added
 - Status changed from RESOLVED to VERIFY_FAILED
 - Assignee changed from CD TEST-方永红 to CD FW 曹覃刚

4.23

【复现版本】

FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103.202304210449

【日志】

ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_117584

#4 - 2023-04-23 17:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195639	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:SystemUI: add default resource definition for Screen record UI and Brightness UITC-RID: 1201-0201905IssueID: TS-R-BUG-117584Change-Id: Iaf77b1b35e2c421ba9ad835ab9be6d62f3df3c71			

- #5 - 2023-04-23 17:38 - CD FW 曹覃刚
- Status changed from VERIFY_FAILED to RESOLVED
 - Fixed Version changed from 2023-04-21 to 2023-04-24
 - Root cause changed from 与#117573 原因一致，已修复 to 默认资源未定义，已添加默认资源
- #6 - 2023-04-24 10:23 - CD TEST-方永红
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- #7 - 2023-04-25 18:35 - CD TEST-方永红

4.25
24日版本冒烟失败，待今日跑测后更新

#8 - 2023-04-26 11:25 - CD TEST-方永红

4.26
0094版本未复现

#9 - 2023-04-27 13:57 - CD TEST-方永红

4.27
26号DB版本未复现、继续跟踪一个版本

#10 - 2023-04-28 17:28 - CD TEST-方永红
- Verified Version set to FlatBuild_HH_MCE_FSE.M.R.user.01.00.0095.C103(X103)

4.28
27日DB未复现
先关闭

#11 - 2023-04-28 17:28 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#12 - 2023-04-28 17:28 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
tlog_sts40x190067_000135_0419175931.tar.gz	7.01 MB	2023-04-20	CD TEST-方永红
error(1).txt	2.53 MB	2023-04-20	CD TEST-方永红
error.txt	200 KB	2023-04-23	CD TEST-方永红