Figure - Bug #117614

[VXMCE-583] 【FSE-M】【OTA刷写】刷写失败

2023-04-21 11:03 - 物联网测试组_TSCD 王维

Status: CLOSED Start date: 2023-04-21

Due date:

Priority: Normal

Assignee:物联网测试组_TSCD 王维% Done:0%Category:依赖客户及其供应商解决Estimated time:0.00 hour

Target version:

Need_Info:
- Found Version:
无

Resolution:
- Degrated:
-

Severity:NormalVerified Version:Reproducibility:Every timeFixed Version:Test Type:STRoot cause:

Description

使用0x1C2002作为一个块刷写,3601必现无响应

使用0xFEB02作为一个块刷写,几率性在某一个块刷写失败

History

#1 - 2023-04-21 11:04 - 物联网测试组_TSCD 王维

- Status changed from NEED_INFO to RESOLVED

由客户解决

#2 - 2023-04-21 11:04 - 物联网测试组_TSCD 王维

- Status changed from RESOLVED to VERIFIED

#3 - 2023-04-21 11:04 - 物联网测试组_TSCD 王维

- Status changed from VERIFIED to CLOSED

Files

VXMCE-583.pdf 132 KB 2023-04-21 物联网测试组_TSCD 王维

2025-07-04 1/1