

Figure - Bug #117649

测试 Test-ST # 111337 (New): ST测试总票
测试 Test-ST # 116840 (New): 中控联调测试-AF

【AF】 【EVT3】 【AUDIO】 副屏voice call的音量和媒体音量不一致

2023-04-24 11:08 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-04-24
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	AUDIO-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-04-25
Reproducibility:	Every time	Root cause:	由于当前的没有headset设备，我们将音量的设置统一为speaker
Test Type:	ST		

Description	
【测试步骤】 1、微信接通电话 2、观察控制中心音量显示 3、挂断电话，观察控制中心音量显示 【预期结果】 3、步骤二三中音量一致 【测试结果】 3、步骤二三中音量不一致	

History

#1 - 2023-04-25 15:20 - Multimedia组-RD3_TSCD 梁卿山

Hi ALL

- 当前问题原因有两个：
- 1.在中控设置副屏音量时， 设置的是voice call流的音量；
 - 2.在副屏语音通话时， 获取的是headset设备的音量， 导致和speaker音量不一致；

由于当前的没有headset设备， 我们将音量的设置统一为speaker；
并修复中控设置副屏音量时， 设置为music流的音量。

#2 - 2023-04-25 19:27 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
196137	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com

#3 - 2023-04-25 19:28 - Multimedia组-RD3_TSCD 梁卿山

- Status changed from New to *RESOLVED*
- Assignee changed from Multimedia组-RD3_TSCD 梁卿山 to CD TEST-方永红
- Resolution changed from -- to *FIXED*
- Degrated changed from -- to No
- Fixed Version set to 2023-04-25
- Root cause set to 由于当前的没有headset设备，我们将音量的设置统一为speaker；并修复中控设置副屏音量时，设置为music流的音量。

HI 永红

该问题修复的代码已经投入，请使用4/25日后的版本进行验证，谢谢！

#4 - 2023-05-05 14:23 - CD TEST-方永红

- Status changed from *RESOLVED* to *VERIFIED*
- % Done changed from 0 to 100

5.5

验证通过

#5 - 2023-05-05 14:23 - CD TEST-方永红

- Status changed from *VERIFIED* to *CLOSED*