

Status:	CLOSED	Start date:	2023-05-04
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0094.c103
Resolution:	DUPLICATE	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
环境信息】EE环境			
【问题出现时间】：20230427 11：08			
【前提条件】：车机上电，蓝牙已开启			
【操作步骤】			
1.副屏蓝牙向中控设备发起蓝牙配对请求			
【实际结果】			
1.配对失败，提示PIN码不正确，无法配对			
【期望结果】			
1.配对成功			
【备注】：			
【影响版本】：01.00.0094.c103			
【硬件版本号】：			
Related issues:			
Related to Figure - Bug # 117740: 【IOVDEV-25051】 【VC1】 【009...		CLOSED	2023-05-04

History

- #1 - 2023-05-04 16:08 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD FW-程天颖
- #2 - 2023-05-04 16:14 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CD LC 陶洪普
- Hi,洪普：
- 副屏蓝牙不应该显示中控设备，需要底层进行屏蔽，请帮忙分析一下
- #3 - 2023-05-04 16:14 - CD FW-程天颖
- Status changed from New to ASSIGNED
- #4 - 2023-05-04 22:47 - CD LC 陶洪普
- Assignee changed from CD LC 陶洪普 to CD TPM-王祥林
- Resolution changed from -- to DUPLICATE

Hi

该问题与

<https://share.thundersoft.com/redmine/issues/117743>

【蓝牙】打开蓝牙，副屏可以搜索到中控设备，并且设备类型显示为耳机
重复（不显示后，不再连接），申请以重复问题关闭，请review，谢谢！

#5 - 2023-05-04 23:56 - CD TPM-王祥林

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD TPM-王祥林 to CDTS_Test 吴诗雨

诗雨

117743需要把中控蓝牙屏蔽掉，这个问题的前提条件就不存了。可以关闭此问题，跟踪117743就可以。

#6 - 2023-05-05 10:45 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

117743跟踪

#7 - 2023-05-05 10:45 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

19f0f500-5649-4acd-8cd7-ecf6f69ebf20.jpg	1.3 MB	2023-05-04	CDTS_Test 吴诗雨
042701.txt	4.03 MB	2023-05-04	CDTS_Test 吴诗雨