

Status:	CLOSED	Start date:	2023-05-05
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0094.c103
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-05-06
Test Type:	ST	Root cause:	系统不支持通知延迟操作。
Description			
环境信息】EE环境			
【问题出现时间】：20230430 13：34			
【前提条件】：车机上电，通知设置中的“允许显示通知延后选项”是关闭状态			
【操作步骤】			
1.通知设置中心开启“允许显示通知延后选项”			
2.进入通知中心，选择任一应用通知的延后按钮进行点击			
【实际结果】			
1.点击延后按钮无效，不能设置应用通知的延后时间			
【期望结果】			
1.点击延后按钮后可以正常设置应用通知的延后时间			
【影响版本】：01.00.0094.c103			
【硬件版本号】			

History
#1 - 2023-05-05 19:05 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

Hi 涛哥

通知菜单只支持删除和设置两种，其他的类型的通知菜单需要禁用

麻烦做下处理

#2 - 2023-05-06 14:01 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
197723	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Remove snooze notification preference.TC-RID: 1201-0201803IssueID: TS-R-BUG-117764Change-Id:			

#3 - 2023-05-06 14:03 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-06
- Root cause set to 系统不支持通知延迟操作。

■ Current conclusion

已处理，代码已入库。

■ My analysis

系统不支持通知延迟操作，已在设置中禁用 允许通知延迟选项 开关。

■ Next action

测试验证。

#4 - 2023-05-09 15:26 - CDTS_Test 吴诗雨

验证通过，待客户验证

#5 - 2023-05-09 15:26 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to NEED_INFO

#6 - 2023-05-17 16:39 - CDTS_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

#7 - 2023-05-17 16:39 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#8 - 2023-05-17 16:39 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

点击延后按钮无效.mp4	19.7 MB	2023-05-05	CDTS_Test 吴诗雨
--------------	---------	------------	---------------