

Status:	CLOSED	Start date:	2023-05-05
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0094.C103
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【环境信息】EE环境 【问题出现时间】：20230504 17：33 【前提条件】：车机上电 【操作步骤】 1. 中控屏进入设置-驾驶，开启续航增加，查看副屏 【实际结果】 1.副屏没有熄屏 【期望结果】 1.副屏熄屏 【车架号】： 【影响版本】：01.00.0094.C103 【硬件版本号】：/ 【是否能恢复】：可恢复			

History

- #1 - 2023-05-06 18:12 - CD TPM-王祥林
- Assignee changed from CD TPM-王祥林 to CD FW-程天颖
- #2 - 2023-05-08 15:58 - CD FW-程天颖
- Category changed from CD-FW to 依赖客户及其供应商解决
- Status changed from New to ASSIGNED
- 已和中控开发确认，请转给华人运通闫红旭
- #3 - 2023-05-08 15:58 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CDTS_Test 吴诗雨
- #4 - 2023-05-17 16:38 - CDTS_Test 吴诗雨
- Status changed from ASSIGNED to RESOLVED
- #5 - 2023-05-17 16:38 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

#6 - 2023-05-17 16:38 - CDTS_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

Files			
17点33分中控屏开启续航增加，副屏没有熄屏.7z	168 KB	2023-05-05	CDTS_Test 吴诗雨
中控屏开启续航增加，副屏没有熄屏.mp4	7.52 MB	2023-05-05	CDTS_Test 吴诗雨