

Status:	CLOSED	Start date:	2023-05-08
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	03.02.0076.C101
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-05-12
Test Type:	ST	Root cause:	发送给中空的数据错误
Description			
【环境信息】EE环境 【问题出现时间】：20230505 19：04 【前提条件】：车机上电 【操作步骤】 1.副屏进入控制中心点击熄屏 【实际结果】 1.副屏熄屏，中控屏设置-显示的熄屏模式中“仅副驾屏”未高亮显示 【期望结果】 1.副屏熄屏，中控屏设置-显示的熄屏模式中“仅副驾屏”高亮显示 【车架号】： 【备注】： 视频地址： 【影响版本】：03.02.0076.C101 【硬件版本号】：/ 【是否能恢复】：			
Related issues:			
Related to Figure - Bug # 117814: 【IOVDEV-25875】【VC1】【007...		CLOSED	2023-05-08

History	
#1 - 2023-05-09 11:22 - CD FW-程天颖	
- Category changed from CD-FW to 依赖客户及其供应商解决	
- Status changed from New to ASSIGNED	
- Assignee changed from CD FW-程天颖 to CDTs_Test 吴诗雨	
- Root cause set to 副屏屏幕状态变更，有同步信息给中控，中控未及时响应	
Hi 诗雨：	
经过分析，副屏屏幕状态变更，有同步信息给中控，中控未及时响应，属于中控的问题，请转给中控研发	
#2 - 2023-05-09 13:56 - CDTs_Test 吴诗雨	
- Status changed from ASSIGNED to RESOLVED	

中控问题，关闭bug

#3 - 2023-05-09 13:56 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

#4 - 2023-05-09 13:56 - CDTS_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

#5 - 2023-05-11 16:45 - CDTS_Test 吴诗雨
- Category changed from 依赖客户及其供应商解决 to CD-FW
- Status changed from CLOSED to New
- Assignee changed from CDTS_Test 吴诗雨 to CD FW-程天颖

yanhongxu：副屏虽然向中控发了副屏的息屏状态，但是协议内容是错的，请检查下发过来的json

#6 - 2023-05-12 10:13 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
199504	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl: Fixed Screen display report message errorTC-RID: 1201-0206101IssueID: TS-R-BUG-117815Change-Id: I62c56e981ae72a5e22bf930389f436986327d781			

#7 - 2023-05-12 10:17 - CD FW-程天颖
- Status changed from New to RESOLVED
- Assignee changed from CD FW-程天颖 to CDTS_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-12
- Root cause changed from 副屏屏幕状态变更，有同步信息给中控，中控未及时响应 to 发送给中空的数据错误

■ Current conclusion
bug已修复
■ My analysis
发送给中空的数据错误
■ Submit URL
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/VehicleControl/+199504>

#8 - 2023-05-17 11:38 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

#9 - 2023-05-17 11:39 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

副屏熄屏后，中控屏显示“仅副驾屏”未高亮.mp4	10.7 MB	2023-05-08	CDTS_Test 吴诗雨
19点04分副屏熄屏后，中控屏下按时仅副驾屏未高亮.7z	338 KB	2023-05-08	CDTS_Test 吴诗雨