

Status:	CLOSED	Start date:	2023-05-08
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	03.02.0076.C101
Resolution:	--	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Occasionally	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【问题描述】：连续点击电源键，副屏息屏后不亮屏 【前置条件】：车辆上电 【软件/网络环境】：EE环境 【软件版本】：IDCM 03.02.0076.C101 【提报人】：李清鑫 【操作步骤】：1.连续点击电源键 【预期结果/行为】：电源键连续点击副屏息屏后亮屏 【实际结果/行为】：副屏息屏后不亮屏 【问题发生频率】：偶现 【实车VIN】：LJD8BC3F7P0000360 【发生日期 & 时间】：2023/05/07 16:52 【数采仪编号】：0300142 【视频链接】：见附件			

History

- #1 - 2023-05-09 10:03 - CD FW-廖涛
- Status changed from New to ASSIGNED
- Assignee changed from CD FW-程天颖 to CD FW-廖涛
- #2 - 2023-05-09 14:37 - CD FW-廖涛
- Status changed from ASSIGNED to NEED_INFO
- Assignee changed from CD FW-廖涛 to CDTs_Test 吴诗雨

■ Current conclusion

我这边使用遥控器 Demo App 进行测试，表现正常，未出现无法点亮副屏的问题。

■ My analysis

通过我自己使用中控遥控器测试，中控遥控器的电源按钮点击区域仅在图标大小内，快速点击可能出现未点中的情况。

■ Next action

麻烦测试跟客户沟通下，要下副屏和中控的日志。

#3 - 2023-05-23 13:51 - CDTs_TEST 王成

客户回复：如三个版本不复现，直接关闭相关问题。

#4 - 2023-06-03 17:43 - CD TEST-方永红
- Status changed from NEED_INFO to RESOLVED

6.3
客户已关闭，同步关闭

#5 - 2023-06-03 17:44 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#6 - 2023-06-03 17:44 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files				
image-2023-05-08-10-27-26-630.png	173 KB	2023-05-08	CDTS_Test 吴诗雨	
image-2023-05-08-10-33-39-168.png	382 KB	2023-05-08	CDTS_Test 吴诗雨	
新视频9.mp4	5.39 MB	2023-05-08	CDTS_Test 吴诗雨	