

Status:	CLOSED	Start date:	2023-05-10
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	【中控版本号】：03.02.0078.x101 【副屏版本号】：01.00.0095.c103
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-05-12
Test Type:	ST	Root cause:	AOSP 原生问题，返回按钮和图标的间隔太小。
Description			
【环境信息】EE环境			
【问题出现时间】：20230509 16:59			
【前提条件】：副屏上电			
【操作步骤】			
1.点击相册APP-查看图片			
【实际结果】			
1.相册图标和左上角返回按钮重叠			
【期望结果】			
1.相册图标和返回按钮不应重叠			
【备注】：			
【应用版本】：			
【VIN号】：LJD8BC3F6P0000365			
【中控版本号】：03.02.0078.x101			
【副屏版本号】：01.00.0095.c103			

History

#1 - 2023-05-12 09:52 - CD APP-王营

- Status changed from New to ASSIGNED

- Assignee changed from CD APP- 王营 to CD FW- 廖涛

#2 - 2023-05-12 15:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199691	general/platform/packages/apps/Gallery2	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF: Gallery2: Fix action bar navigation icon overlap problem.TC-RID: 0301-0300701IssueID: TS-R-BUG-117862Change-Id:

#3 - 2023-05-12 15:19 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CDTS_Test 吴诗雨
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-12
- Root cause set to AOSP 原生问题，返回按钮和图标的间隔太小。

■ Current conclusion

已处理，代码已入库。

■ My analysis

AOSP 原生问题，返回按钮和图标的间隔太小。已调整间距。

■ Next action

测试验证。

#4 - 2023-05-17 10:07 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to NEED_INFO

验证通过，待客户验证

#5 - 2023-05-17 16:10 - CDTS_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

#6 - 2023-05-17 16:10 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#7 - 2023-05-17 16:11 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

副屏-相册.jpg	359 KB	2023-05-10	CDTS_Test 吴诗雨
-----------	--------	------------	---------------