

Figure - Bug #117865

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT】【桌面】概率出现（1/10），本地视频播放中，断电重启后出现开机引导

2023-05-10 18:18 - 物联网测试组_CDTS 唐霞

Status:	CLOSED	Start date:	2023-05-10
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0098.C103(X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-05-12
Reproducibility:	Rarely	Root cause:	异常断电的情况下 Provision 引导程序没有禁用成功
Test Type:	Release Test		
Description			
【测试步骤】 本地视频播放中，断电重启 【预期结果】 重启后进入桌面显示正确 【测试结果】 重启后出现开机引导			

History

#1 - 2023-05-11 15:56 - CD FW-廖涛

- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛
- Priority changed from High to Normal

Current conclusion

由于通过中控正常激活，不会出现断电后再次进入激活引导页面的问题，且该问题为低概率问题，所以申请降低问题优先级。

High -> Normal

#2 - 2023-05-11 15:56 - CD FW-廖涛

- Severity changed from Major to Normal

#3 - 2023-05-12 10:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199516	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:FactoryMode: Fix abnormal launch activation page problem.TC-RID: 1201-0207601IssueID: TS-R-BUG-117865Change-Id: Ie6a842cba24a2cefcfffd2da48c47f956379af8e			

#4 - 2023-05-12 10:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199517	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:FactoryMode: Fix abnormal launch activation page problem.TC-RID: 1201-0207601IssueID: TS-R-BUG-117865Change-Id: I65c0ab45f94db187117bededa0236d5b390304b6			

#5 - 2023-05-12 10:11 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to 物联网测试组_CDTS 唐霞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-12
- Root cause set to 异常断电的情况下 Provision 引导程序没有禁用成功。

■ Current conclusion

已处理，代码已入库。

■ My analysis

异常断电的情况下 Provision 引导程序没有禁用成功。

已跟进跳过激活的属性状态来关闭激活引导页面。

■ Next action

测试验证。

#6 - 2023-05-15 19:18 - 物联网测试组_CDTS 唐霞

- Status changed from RESOLVED to VERIFIED

验证通过，关闭问题单

验证版本：FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103.202305150054

#7 - 2023-05-15 19:18 - 物联网测试组_CDTS 唐霞

- Status changed from VERIFIED to CLOSED