

Status:	CLOSED	Start date:	2023-05-11
Priority:	High	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	03.02.0078.C101.SE
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
Test Sequence:			
■Precondition:			
1、电源模式on，仪表点亮			
■Connected Devices:（串口）			
■Steps:（测试步骤）			
1.正常钥匙解锁车辆			
Actual behaviour:			
1.车辆解锁后中控仪表亮起，副屏未亮起，手触副屏无反应，touch无效，反复锁车解锁后可以复归			
Expected behaviour:			
1.副屏可以正常亮起			
■Requirement：			
■Test Case ID:			
Hardware version:			
Software version: 03.02.0078.C101.SE			
■Recovery:同测试步骤			
■Reproduce rate: 1/10			
■Tester and tel: 童丽丽			
■Comments:2023-5-10			

History

- #1 - 2023-05-12 11:14 - CD TPM-王祥林
- Status changed from New to NEED_INFO
- Assignee changed from CD TPM-王祥林 to CDTS_Test 吴诗雨

请客户提供以下信息：

1.请提供一下副屏的版本号和日志。

2.0095之前的版本，解锁后副屏有大概十几秒的黑屏时间，然后才是开机动画，请确认解锁后等了多长时间发现仍然是黑屏的。

- #2 - 2023-05-18 21:32 - CDTS_Test 吴诗雨
- Priority changed from Normal to High
- Severity changed from Normal to Major

#3 - 2023-05-23 21:13 - CDTS_TEST 王成

客户反馈使用的副屏版本为0068，等客户更新版本后再次验证

#4 - 2023-06-03 15:59 - CD TEST-方永红

6.3
等待客户验证验证中

#5 - 2023-07-04 18:22 - CDTS_TEST 王成
- Status changed from NEED_INFO to RESOLVED

客户反馈：需要更新副屏硬件和软件，待新车到位后进行验证

#6 - 2023-07-04 18:22 - CDTS_TEST 王成
- Status changed from RESOLVED to VERIFIED

#7 - 2023-07-04 18:22 - CDTS_TEST 王成
- Status changed from VERIFIED to CLOSED

Files			
微信图片_20230510142407.jpg	476 KB	2023-05-11	CDTS_Test 吴诗雨