

Figure - Bug #117944

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【IOVDEV-27599】【副屏】设置-关于本机-重命名后，文件中相应名称未及时同步

2023-05-15 21:14 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-05-15
Priority:	Normal	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C103(X103)
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
【详情见截图】			

History

- #1 - 2023-05-16 15:12 - CD FW 曹覃刚
- Category changed from CD-FW to 依赖客户及其供应商解决
 - Status changed from New to NEED_INFO
 - Assignee changed from CD FW 曹覃刚 to CDTS_TEST 王成

Hi 王成

修改设备名称后，重启后，文件应用中的设备名称才会更新

这个是原生逻辑，在对比测试平板中是一样的，联想小新平板也一样(永红测试的)

请帮助同步此信息给客户，谢谢

- #2 - 2023-05-17 15:10 - CDTS_TEST 王成
- Status changed from NEED_INFO to RESOLVED

- #3 - 2023-05-17 15:10 - CDTS_TEST 王成
- Status changed from RESOLVED to VERIFIED

- #4 - 2023-05-17 15:18 - CDTS_TEST 王成
- Status changed from VERIFIED to CLOSED

Files

Snipaste_2023-05-15_21-11-16.png	411 KB	2023-05-15	CD TEST-方永红
Phone-1A221229000002271 2023-05-15 21-13-33.mp4	14.1 MB	2023-05-15	CD TEST-方永红