

Status:	CLOSED	Start date:	2023-05-16
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	01.00.0095.c103
Resolution:	FIXED	Degraded:	No
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	2023-05-22
Test Type:	Free Test	Root cause:	原本默认没有信号时是不显示图标的，现在增加无
Description			
【环境信息】EE环境 【问题出现时间】：20230516 8:50 【前提条件】：车机上电（KL30ON，KL15 ON），连接以太网（中控显示5G信号） 1. 检查副屏状态栏 【实际结果】 副屏显示同步中控的以太网图标类同WiFi图标，且没有显示5G标志。 【期望结果】 副屏同步中控的以太网5G信号，正确显示5G图标 【车架号】： 【备注】： log地址：https://ofs.human-horizons.com/#/download/index/9234KfxIHQU%3D 视频地址：https://ofs.human-horizons.com/#/download/index/Lzpvoty29X8%3D 【影响版本】：副屏：01.00.0095.c103 【硬件版本号】：/ 【是否能恢复】：			

History
#1 - 2023-05-17 16:02 - CDTs_TEST 王成
ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_117984/tlog_iov0201017500006162025411a2212290000000911_000139_0516090347.tar.zip 日志FTP地址
#2 - 2023-05-17 21:42 - CDTs-TEST 周婷
- Category changed from ETH to CD-FW
- Assignee changed from CD_BSP 彭文亮 to CD FW 曹覃刚
#3 - 2023-05-18 10:20 - CD FW 曹覃刚
- Status changed from New to ASSIGNED

- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖

#4 - 2023-05-20 17:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
201461	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:VehicleDataControl: Fixed tbox have no none-server iconTC-RID: 1201-0206101IssueID: TS-R-BUG-117984Change-Id: I1ae10e5f346b9b73d58205224656f0a5d5ce45a1			

#5 - 2023-05-20 17:39 - CD FW 曹覃刚

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-程天颖 to CDTS-TEST 周婷
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-05-22
- Root cause set to 原本默认没有信号时是不显示图标的，现在增加无信号时的图标

#6 - 2023-06-02 18:46 - CD TEST-方永红

- Status changed from RESOLVED to VERIFY_FAILED
- Assignee changed from CDTS-TEST 周婷 to CD FW 曹覃刚

未显示 “ 无服务 ” 图标

#7 - 2023-06-02 18:56 - CD FW 曹覃刚

- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖

#8 - 2023-06-02 19:01 - CD TEST-方永红

- Status changed from VERIFY_FAILED to VERIFIED
- Assignee changed from CD FW-程天颖 to CD TEST-方永红

#9 - 2023-06-02 19:01 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#10 - 2023-06-03 16:34 - CD TEST-方永红

- File icon.txt added
- File 中控5G，副屏显示无服务.mp4 added
- Status changed from CLOSED to New

6.3
客户实车验证失败

#11 - 2023-06-03 17:10 - CD FW-田成财

■ Current conclusion

已分析出原因

■ My analysis

中控同步的tbox信号的IDCM_celltype为-1，根据协议定义，5g应该为6，并且无-1的定义，所以把该信号识别为无服务。
06-03 16:26:24.369 2148 17255 I MicroService: Receive message: SocketMessageBean{businessData='21930', srcService='IDCM_TBoxService', destService='FSEM_SettingService', messageType='0', uuid='1685780784862430000', payloadData={"dstService":"FSEM_SettingService","messageType":0,"methodName":"netstatus","parameters":{"functionInfo":{"IDCM_celltype":-1,"IDCM_netstatus":-1,"IDCM_signalstrength":-1},"srcService":"IDCM_TBoxService","uuid":"1685780784862430000"}}

■ Next action

请中控的tbox研发进行确认

#12 - 2023-06-04 00:24 - CD TPM-王祥林
- Status changed from New to NEED_INFO

#13 - 2023-06-05 13:44 - CD TEST-方永红

6.5
已流转至中控研发处，等待确认后关闭

#14 - 2023-07-03 16:21 - CD TEST-方永红
- Status changed from NEED_INFO to RESOLVED

7.3
验证通过

#15 - 2023-07-03 16:21 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#16 - 2023-07-03 16:21 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
同步无网络的以太网信号，显示图标不正确 (1).mp4	10 MB	2023-05-16	CDTS-TEST 周婷
icon.txt	7.04 MB	2023-06-03	CD TEST-方永红
中控5G，副屏显示无服务.mp4	2.41 MB	2023-06-03	CD TEST-方永红