

Figure - Bug #117985

【IOVDEV-28389】【VCI】【内部】【0095】【台架】【EE环境】【副屏】【第三方应用】应用宝-点击应用详情后退出-UI不兼容，退出键被上方横框遮挡，无法退出

2023-05-16 21:28 - 物联网测试组_TSCD 王维

Status:	CLOSED	Start date:	2023-05-16
Priority:	Normal	Due date:	
Assignee:	CD FW 曹覃刚	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	应用宝版本号：8.4.2副屏版本号：01.00.0095.C
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	ST		
Description			
详情 类型: 故障 状态:开放 (查看工作流) 优先级: C 解决结果:未解决 影响版本: 03.02.0080.C101 修复的版本:无 模块: 副屏 标签:无 Repetition Rate: 3/3 测试环境:台架手动测试 项目名: VCI 描述 【台架号】：HRYTTESTVINMGM441 【环境信息】：EE环境 【测试时间】：2023.5.16 【前提条件】：1、网络正常 2、副屏上电 【操作步骤】 1、点击应用详情后退出 【实际结果】 UI不兼容，退出键被上方横框遮挡，无法退出 【期待结果】 正常加载进入 【备注】：			

应用宝版本号：8.4.2
副屏版本号：01.00.0095.C103
台架vin号：HRYTTESTVINMGM441

History

#1 - 2023-05-16 22:06 - CDTS_TEST 王成

- Status changed from New to RESOLVED

0100版本修复

#2 - 2023-05-16 22:06 - CDTS_TEST 王成

- Status changed from RESOLVED to VERIFIED

#3 - 2023-05-16 22:06 - CDTS_TEST 王成

- Status changed from VERIFIED to CLOSED

Files

image-2023-05-16-15-50-39-266.png	59.6 KB	2023-05-16	物联网测试组_TSCD 王维
-----------------------------------	---------	------------	----------------