

Status:	CLOSED	Start date:	2023-05-17
Priority:	Normal	Due date:	
Assignee:	CDTS-TEST 周婷	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	03.02.0080.C101
Resolution:	FIXED	Degrated:	No
Severity:	Major	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	2023-05-12
Test Type:	Free Test	Root cause:	上报给中控的数据不对
Description			
【HiPhiUI】【系统设置】副驾息屏BTN回弹			
【车架号】：HRYTTESTVINMGM817			
【环境信息】：EE环境			
【问题出现时间】：20230516 14.28			
【前提条件】：1、车机上电			
【操作步骤】1、进入设置-显示-开启副驾息屏			
【实际结果】1、按钮回弹			
【期望结果】1、按钮高亮			
【备注】：UX_VC1_11_系统设置_V0.1.3_20230131			
PRD_MCE_系统设置_V0.2.4_20230203			
IDCM_系统设置_系统需求文档_v1.3			
【版本详情】			
影响版本：03.02.0080.C101			
【硬件版本号】B样			
v-HongxuYan 麻烦看下这个副驾息屏开关回弹问题，设置下发了启用息屏模式，但是一会就上报了回弹			
固定链接			
HongxuYan			
v-HongxuYan 添加了评论 - 2023/05/17 09:38 - 已编辑			
1.MultiScreen在发送息屏失败，副屏没有通知MultiScreen息屏状态时，当作此次息屏失败，通知App开关回弹			
2.此次副屏发送过来的息屏协议错误，也当作是失败，所以通知回弹			
05-16 14:32:19.952 2593 2784 D MultiScreen_ComhalReceiver: onReceiveData			

05-16 14:32:19.952 2593 2784 D MultiScreen_ComhalReceiver: onReceiveData data size:192
05-16 14:32:19.952 2593 2784 D MultiScreen_ComhalReceiver: onReceiveData receiveData =
{ "srcService": "FSEM_SettingService", "dstService": "IDCM_MultiScreenService", "messageType": 0, "uuid": "1684218739308583493", "methodName": "reportScreenDisplay", "parameters": { "reportScreenDisplay": 1 } }
05-16 14:32:19.952 2593 2784 W System.err: org.json.JSONException: No value for ScreenDisplay
05-16 14:32:19.952 2593 2784 W System.err: at org.json.JSONObject.get(JSONObject.java:400)
05-16 14:32:19.952 2593 2784 W System.err: at org.json.JSONObject.getString(JSONObject.java:561)
05-16 14:32:19.952 2593 2784 W System.err: at com.hryt.multiScreenService.comhal.ComhalReceiver\$1.onReceiveData(ComhalReceiver.java:68)
05-16 14:32:19.952 2593 2784 W System.err: at vendor.hht.comhal.comhal.V1_0.IComHalListener\$Stub.onTransact(IComHalListener.java:567)

固定链接 编辑 删除

AlexHu1

v-AlexHu1 添加了评论 - 2023/05/17 15:57 - 已编辑

台架上测试需使用以下命令打开息屏按钮后才能使用此功能：

adb root

adb shell

ssh [root@223.255.255.1](#)

dbus-send --bus=tcp:host=223.255.255.1,port=55666 --type=signal / ipcl.out.to.droid.SWC2VHAL_COMM array:byte:3,51,1

固定链接

AriaHu1

Aria HU 胡瑞 添加了评论 - 2023/05/17 16:44

固定链接

AriaHu1

Aria HU 胡瑞 添加了评论 - 2023/05/17 16:46 - 已编辑

video_1684313065.mp4 16.44 VIN同票（此台架已连接副屏）

History

#1 - 2023-05-17 19:26 - CD FW 曹覃刚

- Status changed from New to ASSIGNED

- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖

#2 - 2023-05-17 19:40 - CDTs_TEST 王成

- File video_1684313065.mp4 added

- File video_1684218373.mp4 added

- File image-2023-05-17-16-44-37-482.png added

- File image-2023-05-16-19-46-45-826.png added

1.MultiScreen在发送息屏失败，副屏没有通知MultiScreen息屏状态时，当作此次息屏失败，通知App开关回弹

2.此次副屏发送过来的息屏协议错误，也当作是失败，所以通知回弹

05-16 14:32:19.952 2593 2784 D MultiScreen_ComhalReceiver: onReceiveData

05-16 14:32:19.952 2593 2784 D MultiScreen_ComhalReceiver: onReceiveData data size:192

05-16 14:32:19.952 2593 2784 D MultiScreen_ComhalReceiver: onReceiveData receiveData =

{ "srcService": "FSEM_SettingService", "dstService": "IDCM_MultiScreenService", "messageType": 0, "uuid": "1684218739308583493", "methodName": "reportScreenDisplay", "parameters": { "reportScreenDisplay": 1 } }

05-16 14:32:19.952 2593 2784 W System.err: org.json.JSONException: No value for ScreenDisplay

05-16 14:32:19.952 2593 2784 W System.err: at org.json.JSONObject.get(JSONObject.java:400)

05-16 14:32:19.952 2593 2784 W System.err: at org.json.JSONObject.getString(JSONObject.java:561)

05-16 14:32:19.952 2593 2784 W System.err: at com.hryt.multiScreenService.comhal.ComhalReceiver\$1.onReceiveData(ComhalReceiver.java:68)

- #3 - 2023-05-17 19:45 - CD FW-程天颖
- Status changed from ASSIGNED to NEED_INFO
 - Assignee changed from CD FW-程天颖 to CDTS-TEST 周婷
 - Need_Info changed from -- to TEST

应该在5月12日解决了，001000版本会有该提交，请使用00100版本测试

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/VehicleControl/+199504>

- #4 - 2023-05-18 20:43 - CDTS-TEST 周婷
- Status changed from NEED_INFO to ASSIGNED
 - Assignee changed from CDTS-TEST 周婷 to CD FW-程天颖

走resolve 状态

- #5 - 2023-05-19 17:43 - CD FW-程天颖
- Status changed from ASSIGNED to RESOLVED
 - Assignee changed from CD FW-程天颖 to CDTS-TEST 周婷
 - % Done changed from 0 to 100
 - Need_Info changed from TEST to --
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Fixed Version set to 2023-05-12
 - Root cause set to 上报给中控的数据不对

- Current conclusion
- 应该在5月12日解决了，001000版本会有该提交，请使用00100版本测试
- My analysis
- 上报给中控的数据不对
- Submit URL
- <https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/VehicleControl/+199504>

- #6 - 2023-06-02 19:14 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

6.2

验证通过

- #7 - 2023-06-02 19:15 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
video_1684313065.mp4	894 KB	2023-05-17	CDTS_TEST 王成

video_1684218373.mp4	2.47 MB	2023-05-17	CDTS_TEST 王成
image-2023-05-17-16-44-37-482.png	54.6 KB	2023-05-17	CDTS_TEST 王成
image-2023-05-16-19-46-45-826.png	115 KB	2023-05-17	CDTS_TEST 王成