

Status:	CLOSED	Start date:	2023-05-17
Priority:	Normal	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	0%
Category:	依赖客户及其供应商解决	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	0095
Resolution:	DUPLICATE	Degrated:	--
Severity:	Normal	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	
Description			
【车辆VIN】LJD8BC3F6P0000382 【问题时间】2023.5.8 2:04PM 【车辆环境】EE 【前提条件】 1、整车上电ON 2、多媒体功能正常 【操作步骤】 1、顶部下拉进入副屏控制中心页面 2、拖动亮度条至最左边 3、设置打开自动亮度，查看副屏亮度变化 【期望结果】副屏亮度有变化 【实际结果】副屏亮度无变化 【复归方法】无 【复现率】5/5 【备注】副屏版本0095			

History

#1 - 2023-05-17 21:03 - CDTs_TEST 王成

ftp://cdiot@192.168.87.46/Pre_figure/Test_Log/Bug_118019/372%E8%BD%A65.17.7z

#2 - 2023-05-17 21:23 - CD FW 曹覃刚

- Category changed from CD-FW to 依赖客户及其供应商解决
- Status changed from New to NEED_INFO
- Assignee changed from CD FW-程天颖 to CDTs_TEST 王成

Hi 王成

该问题应该已经修复了, 请让客户使用最新的版本测试, 谢谢

05/10投入的提交, 与 #117843 相同

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/VehicleControl/+/199023>

#3 - 2023-06-03 17:38 - CD TEST-方永红

- Status changed from NEED_INFO to RESOLVED

#4 - 2023-06-03 17:38 - CD TEST-方永红
- Resolution changed from -- to DUPLICATE

#5 - 2023-06-03 17:39 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#6 - 2023-06-03 17:39 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
副屏自动亮度.mp4	9.26 MB	2023-05-17	CDTS_TEST 王成