

Figure - Bug #118024

测试 Test-IT # 111062 (New): V3.0功能测试
测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT】【小窗模式】打开音乐小窗，进入mini小窗模式动画异常（在mini小窗下点击页面空白处有选中列表中的歌曲）

2023-05-18 11:09 - 物联网测试组_CDTS 唐霞

Status:	CLOSED	Start date:	2023-05-18
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 唐霞	% Done:	0%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_MCE_FSE.M.R.user.01.00.0101C103(X
Need_Info:	TEST	Degrated:	--
Resolution:	WONTFIX	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	问题产生的原因是由于在切换到mini态的时候,窗口
Test Type:	Release Test		
Description			
【测试步骤】 打开音乐小窗， 点击进入mini小窗按钮 【预期结果】 小窗进入mini小窗模式且动画正常 【测试结果】 小窗进入mini小窗后画面闪动了2下 在mini小窗下点击页面空白处有选中列表中的歌曲			

History

#1 - 2023-05-18 11:28 - CD FW-廖涛

- Status changed from New to ASSIGNED
- Assignee changed from CD FW-廖涛 to CD FW 曹覃刚

#2 - 2023-05-19 09:53 - CD FW 曹覃刚

- Assignee changed from CD FW 曹覃刚 to CD FW-鲁凯峰

#3 - 2023-05-20 10:41 - CD FW-鲁凯峰

- Status changed from ASSIGNED to NEED_INFO
- Assignee changed from CD FW-鲁凯峰 to 物联网测试组_CDTS 唐霞
- Need_Info changed from -- to TEST
- Resolution changed from -- to WONTFIX
- Root cause set to 问题产生的原因是由于在切换到mini态的时候,窗口的大小发生了变化, Music这边为了适应新的窗口大小,内部会做一些刷新视图的动作,所以能看到播放详情界面有个适配的过程,就是抽屉会刷新一下,这个是必要的动作,必须刷新来确定当前的界面显示正确,不能因为窗口大小发生变化而出现显示不全的问题.

目前的是不推荐修改该问题,理由如下

1. 问题产生的原因是由于在切换到mini态的时候,窗口的大小发生了变化, Music这边为了适应新的窗口大小,内部会做一些刷新视图的动作,所以能看到播放详情界面有个适配的过程,就是抽屉会刷新一下,这个是必要的动作,必须刷新来确定当前的界面显示正确,不能因为窗口大小发生变化而出现显示不全的问题.
2. 问题现象不是很明显,对用户基本不会造成任何影响

#4 - 2023-05-23 19:00 - 物联网测试组_CDTS 唐霞
- Status changed from *NEED_INFO* to *RESOLVED*

研发建议不修改，关闭问题单

#5 - 2023-05-23 19:00 - 物联网测试组_CDTS 唐霞
- Status changed from *RESOLVED* to *VERIFIED*

#6 - 2023-05-23 19:01 - 物联网测试组_CDTS 唐霞
- Status changed from *VERIFIED* to *CLOSED*

Files			
中科创达软件股份有限公司20230518-110841.mp4	7.72 MB	2023-05-18	物联网测试组_CDTS 唐霞