

Status:	CLOSED	Start date:	2023-05-19
Priority:	High	Due date:	
Assignee:	CD TPM-王祥林	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	03.02.0080.C101
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	ST	Root cause:	

Description

【问题描述】：副驾显示屏启动慢

【软件/网络环境】：EE环境

【IDCM版本】：IDCM 03.02.0080.C101

【试驾人】：杜林林

【实车VIN】：LJD8BC3F7P0000700

【数采仪编号】：0300117

【发生日期 & 时间】：2023/05/16/ 18:51

【问题来源】：VC1 路试问题跟踪

History

#1 - 2023-05-19 19:32 - CD TPM-王祥林

请提供一下副屏的软件版本号，和问题的现象。是从上电到进入主界面的时间慢吗，具体时间是多长。

#2 - 2023-05-19 20:30 - CD TPM-王祥林

- Status changed from New to NEED_INFO

#3 - 2023-05-25 19:32 - CDTS_Test 吴诗雨

客户bug已解决状态，关闭bug

#4 - 2023-05-25 19:34 - CDTS_Test 吴诗雨

- Status changed from NEED_INFO to RESOLVED

#5 - 2023-05-25 19:34 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

#6 - 2023-05-25 19:34 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files

700 副屏启动慢.png	976 KB	2023-05-19	CDTS_Test 吴诗雨
---------------	--------	------------	---------------